

Foothills Helicopter Training academy

Unit 35, 4 Winters Way
Okotoks, AB T1S0J1
Jacki • Jacki@foothillsheli.com
AMO#: 64-23



Reminders

Report date: September 14, 2023

Included in this report:

C-GHCT

C-GHCT

Airbus Helicopters AS350BA (FX2) 1271

ELL: 18138.0 • HOOK HOURS: 1952.5 • LANDINGS: 80845 • NG CYCLES: 15571.0 • NP CYCLES: 15917.05 • TTAF: 19644.4 • ENG TT: 14982.8 • TORQUE CYCLES: 98983.0

LTS101-700D-2, Turbine Engine: 967.1 SINCE OVERHAUL (ENG TT), 14982.8 SINCE NEW (ENG TT) • 753.3 SINCE OVERHAUL (NG CYCLES), 15571.0 SINCE NEW (NG CYCLES) • 837.85 SINCE OVERHAUL (NP CYCLES), 15917.05 SINCE NEW (NP CYCLES) • 967.1 SINCE OVERHAUL (TTAF), 14982.8 SINCE NEW (TTAF)

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|----------------------|---------------|--|-----------------------------|--------------------------|--------------------|--------------------|---|
| 3000HR/72 Month Anti-Vibrator Inspection MSM 05-25-00, 62-20 (350A31-0033-01, Antivibrator Assy., SN: VIK42243) | Expired In Tolerance | TTAF: 19644.4 | 358.0 TTAF or 5 months ago / 44 days tolerance remaining | 20002.4 TTAF or 30 Apr 2023 | 72 months or 3000.0 TTAF | April 26, 2017 | 17002.4 TTAF | |
| AD F-2004-055 - REPLACEMENT OF HYDRAULIC FLUID IN FORECAST CONDITIONS BELOW 15F F-2004-055 | Green | TTAF: 19644.4 | 62.2 TTAF or 10 days | 19706.6 TTAF or 25 Sep 2023 | 30 days or 110.0 TTAF | August 26, 2023 | 19596.6 TTAF | |
| 30 Day ELT function check (Artex ME406) 453-6604 (ELT (Artex ME406), 453-6604, SN: 188-09063) | Green | | 11 days | 26 Sep 2023 | 1 month | August 26, 2023 | | |
| 30 DAY INSPECTION Fire Extinguisher (Amerex) A620T G18295652 | Green | | 15 days | 30 Sep 2023 | 30 days | August 26, 2023 | | |
| RG355 Battery Capacity Check. (STC SR09185RC) 40811414 | Yellow | | 15 days | 30 Sep 2023 | 3 months | June 15, 2023 | | Battery found to be 88% so 3 Month interval. Erase this MOC once complete. - Brydon |
| 12M Onboard System Fuel Drain Guard Inspection STC SR1588SE | Green | | 4 months | 31 Dec 2023 | 12 months | December 21, 2022 | | |
| 12 MONTH INSPECTION Fire Extinguisher (Amerex) A620T G18295652 | Green | | 4 months | 31 Dec 2023 | 12 months | December 21, 2022 | | |
| 12 Month Magnetic Compass Swing Car 625 App C | Green | | 4 months | 31 Dec 2023 | 12 months | December 21, 2022 | | |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------------|------------------------|-----------------------------|--------------------------|--------------------|--------------------|----------------------|
| 12 Month Survival kit Inspection (SURVIVAL KIT, 5K-5MAN, SN: GEM-001) | Green | | 4 months | 31 Dec 2023 | 12 months | December 21, 2022 | | |
| 12M TANIS PREHEAT SYSTEM INSPECTION ICA TCA003 | Green | | 4 months | 31 Dec 2023 | 12 months | December 21, 2022 | | |
| First Aid Kit A122-MH80 | Green | | 4 months | 31 Dec 2023 | 12 months | December 21, 2022 | | |
| 24M DAVTRON M803 BATTERYREPLACEMENT M803 ICA | Yellow | | 5 months | 31 Jan 2024 | 24 months | January 19, 2022 | | |
| 24 Month Altimeter and Altitude Encoder Inspection SSD120-30A A71638 (Altimeter Encoder, SSD120-30A, SN: A71638) | Yellow | | 5 months | 31 Jan 2024 | 24 months | January 19, 2022 | | |
| 24 MONTH ELT INSPECTION (Artex ME406) 453-6604 188-09063 (ELT (Artex ME406), 453-6604, SN: 188-09063) | Yellow | | 5 months | 31 Jan 2024 | 24 months | January 07, 2022 | | |
| 24 Month PITOT - STATIC TEST CAR 571 APPENDIX B and F | Yellow | | 5 months | 31 Jan 2024 | 24 months | January 19, 2022 | | |
| 24 Month Transponder Check GTX32 83724153 (Transponder, GTX32, SN: 83724153) | Yellow | | 5 months | 31 Jan 2024 | 24 months | January 19, 2022 | | |
| 600HR/6 Month MR Blade Pin Greasing MSM 05-25-00, 62-10 | Green | TTAF: 19644.4 | 400.8 TTAF or 5 months | 20045.2 TTAF or 31 Jan 2024 | 6 months or 600.0 TTAF | July 03, 2023 | 19445.2 TTAF | |
| 150H/6M Airframe Inspection (MSM 05-25-00) AS350B2 MSM 05-25-00 | Green | TTAF: 19644.4 | 102.2 TTAF or 5 months | 19746.6 TTAF or 26 Feb 2024 | 6 months or 150.0 TTAF | August 26, 2023 | 19596.6 TTAF | |
| 1000H/12M DART DOME LIGHT AIR VENT STC SH93-82 | Green | TTAF: 19644.4 | 472.0 TTAF or 6 months | 20116.4 TTAF or 29 Feb 2024 | 12 months or 1000.0 TTAF | February 06, 2023 | 19116.4 TTAF | |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------------|-------------------------|-----------------------------|--------------------------|--------------------|--------------------|----------------------|
| 1200H/24M Inspections MSM 05-25-00 (TRGB Casing, TRGB lever, TR Feathering Bearings) | Green | TTAF: 19644.4 | 323.2 TTAF or 7 months | 19967.6 TTAF or 31 Mar 2024 | 24 months or 1200.0 TTAF | March 30, 2022 | 18767.6 TTAF | |
| 12 Month ELT Inspection (Artex ME406) 453-6604 188-09063 (ELT (Artex ME406), 453-6604, SN: 188-09063) | Green | | 7 months | 31 Mar 2024 | 12 months | March 04, 2023 | | |
| AAIR | Green | | 7 months | 31 Mar 2024 | 12 months | March 31, 2023 | | |
| ELT REGISTRATION (SARSAT) | Green | | 7 months | 31 Mar 2024 | 12 months | March 05, 2023 | | |
| 2500HR/72 Month Tailboom-Fuselage Junction Insp. MSM 05-25-00, 53-10 | Red | TTAF: 19644.4 | 59.5 TTAF or 9 months | 19703.9 TTAF or 31 May 2024 | 72 months or 2500.0 TTAF | May 26, 2018 | 17203.9 TTAF | |
| 3000H/72M MGB SUSPENSION CROSS BARINSPECTION AS350B2 MSM 05-25-00 63-30 (350A38-0211-00, Bi-Directional Crossbeam, SN: CHE170394) | Green | TTAF: 19644.4 | 559.5 TTAF or 9 months | 20203.9 TTAF or 31 May 2024 | 72 months or 3000.0 TTAF | May 26, 2018 | 17203.9 TTAF | |
| 600HR/24 Month Airframe Inspection MSM 05-22-00 | Green | TTAF: 19644.4 | 400.8 TTAF or 10 months | 20045.2 TTAF or 03 Jul 2024 | 24 months or 600.0 TTAF | July 03, 2022 | 19445.2 TTAF | |
| 24 Month Airframe Inspection MSM 05-22-02 | Green | | 11 months | 31 Jul 2024 | 24 months | July 28, 2022 | 18886.6 | |
| 600H/12M DART CARGO BASKET INSPECTION STC SH94-14, D350-607-041/045 | Green | TTAF: 19644.4 | 403.7 TTAF or 11 months | 20048.1 TTAF or 31 Jul 2024 | 12 months or 600.0 TTAF | July 12, 2023 | 19448.1 TTAF | |
| 750H/12M PUROLATOR FACET SCAVENGE OIL FILTER STC SH92-36 | Green | TTAF: 19644.4 | 604.3 TTAF or 11 months | 20248.7 TTAF or 31 Jul 2024 | 12 months or 750.0 TTAF | July 18, 2023 | 19498.7 TTAF | |
| 12 Month Airframe Inspection MSM 05-21-02 | Green | | 12 months | 26 Aug 2024 | 12 months | August 26, 2023 | 18886.6 TTAF | |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|--------------------|---------------------------------|-------------------------------------|----------------------------------|--------------------|--------------------|----------------------|
| 100H/12M AIRBUS SETTLING PROTECTORS (BEAR PAWS) STC SH01-22 | Green | TTAF: 19644.4 | 52.2 TTAF or 12 months | 19696.6 TTAF or 31 Aug 2024 | 12 months or 100.0 TTAF | August 26, 2023 | 19596.6 TTAF | |
| 100HH/12M ONBOARD SYSTEMS CARGOHOOK SWING SUSPENSION SYSTEMINSPECTION STC SR01164SE (210- 201-01, Onboard Cargo Swing, SN: 134) | Green | HOOK HOURS: 1952.5 | 61.3 HOOK HOURS or 12 months | 2013.8 HOOK HOURS or 31 Aug 2024 | 12 months or 100.0 HOOK HOURS | August 26, 2023 | 1913.8 HOOK HOURS | |
| 150H/12M AIRBUS BLADE TIE DOWN KIT STC SH96-126 | Green | TTAF: 19644.4 | 102.2 TTAF or 12 months | 19746.6 TTAF or 31 Aug 2024 | 12 months or 150.0 TTAF | August 26, 2023 | 19596.6 TTAF | |
| 150H/12M AIRBUS CARGO MIRROR STC SH96-61 | Green | TTAF: 19644.4 | 102.2 TTAF or 12 months | 19746.6 TTAF or 31 Aug 2024 | 12 months or 150.0 TTAF | August 26, 2023 | 19596.6 TTAF | |
| 150H/12M AIRBUS FLOOR COVERING STC SH12-28 | Green | TTAF: 19644.4 | 102.2 TTAF or 12 months | 19746.6 TTAF or 31 Aug 2024 | 12 months or 150.0 TTAF | August 26, 2023 | 19596.6 TTAF | |
| 150H/12M AIRBUS L/H LITTER KIT STC SH94-29 | Green | TTAF: 19644.4 | 102.2 TTAF or 12 months | 19746.6 TTAF or 31 Aug 2024 | 12 months or 150.0 TTAF | August 26, 2023 | 19596.6 TTAF | |
| 150H/12M AIRBUS REAR CARGO DOOR HINGE STC SH97-33 | Green | TTAF: 19644.4 | 102.2 TTAF or 12 months | 19746.6 TTAF or 31 Aug 2024 | 12 months or 150.0 TTAF | August 26, 2023 | 19596.6 TTAF | |
| 150HR/12 Month Airframe Inspection MSM 05-21-00 | Green | TTAF: 19644.4 | 102.2 TTAF or 12 months | 19746.6 TTAF or 31 Aug 2024 | 12 months or 150.0 TTAF | August 26, 2023 | 19596.6 TTAF | |
| 300H/12M FDC INSPECTION STC SR00811SE/SR01049S E (1350A22-1 FDC Inlet Filter, SN: 00015) | Green | TTAF: 19644.4 | 252.2 TTAF or 12 months | 19896.6 TTAF or 31 Aug 2024 | 12 months or 300.0 TTAF | August 26, 2023 | 19596.6 TTAF | |
| AD CF-2004-10 R1 - HYDRAULIC POWER - SPLINESLUBRICATION CF-2004-10 R1 | Green | TTAF: 19644.4 | 117.2 TTAF or 12 months | 19761.6 TTAF or 31 Aug 2024 | 12 months or 165.0 TTAF | August 26, 2023 | 19596.6 TTAF | |
| 500H/24M HELILYNX DEICING FUEL FILTER STC SH07-31 | Green | TTAF: 19644.4 | 300.8 TTAF or almost 2 years | 19945.2 TTAF or 31 Jul 2025 | 24 months or 500.0 TTAF | July 03, 2023 | 19445.2 TTAF | |
| 500H/24M HELILYNX DIGITAL GAUGES STC SH06-5 & SH06-33 | Green | TTAF: 19644.4 | 300.8 TTAF or almost 2 years | 19945.2 TTAF or 31 Jul 2025 | 24 months or 500.0 TTAF | July 03, 2023 | 19445.2 TTAF | |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|--------|--------------------|----------------------------------|----------------------------------|--------------------------------|--------------------|--------------------|----------------------|
| 600H/24M AIRBUS BLADE TIE DOWN KIT STC SH96-126 | Green | TTAF: 19644.4 | 400.8 TTAF or almost 2 years | 20045.2 TTAF or 31 Jul 2025 | 24 months or 600.0 TTAF | July 03, 2023 | 19445.2 TTAF | |
| 600H/24M DART HELI ACCESS STEP (D350-591-213) STC SH92-6 | Green | TTAF: 19644.4 | 400.8 TTAF or almost 2 years | 20045.2 TTAF or 31 Jul 2025 | 24 months or 600.0 TTAF | July 03, 2023 | 19445.2 TTAF | |
| 600H/24M DART MAINTENANCE STEPS STC SH93-1 | Green | TTAF: 19644.4 | 400.8 TTAF or almost 2 years | 20045.2 TTAF or 31 Jul 2025 | 24 months or 600.0 TTAF | July 03, 2023 | 19445.2 TTAF | |
| 600H/24M DART REAR LOCKER EXTENDER STC SH90-4 | Green | TTAF: 19644.4 | 400.8 TTAF or almost 2 years | 20045.2 TTAF or 31 Jul 2025 | 24 months or 600.0 TTAF | July 03, 2023 | 19445.2 TTAF | |
| 600H/24M DART SKID TUBES STC SH99-7 | Green | TTAF: 19644.4 | 400.8 TTAF or almost 2 years | 20045.2 TTAF or 31 Jul 2025 | 24 months or 600.0 TTAF | July 03, 2023 | 19445.2 TTAF | |
| 1800HR/72M Hydraulic Belt Retirement - Poly V 597K4 (Poly V 597K4, Hydraulic Belt, SN: HCT-2019) | Red | TTAF: 19644.4 | 133.3 TTAF or about 2 years | 19777.7 TTAF or 10 Oct 2025 | 72 months or 1800.0 TTAF | October 10, 2019 | 17977.7 TTAF | |
| 1000HH/60M ONBOARD SYSTEMS TALON LCHYDRAULIC CARGO HOOK SWINGSUSPENSION SYSTEM STC SR01164SE | Yellow | HOOK HOURS: 1952.5 | 158.8 HOOK HOURS or over 2 years | 2111.3 HOOK HOURS or 31 Mar 2026 | 60 months or 1000.0 HOOK HOURS | March 04, 2021 | 1111.3 HOOK HOURS | |
| 1200H/48M TGB OIL CHANGE MSM 05-23-00 65-20 | Green | TTAF: 19644.4 | 323.2 TTAF or over 2 years | 19967.6 TTAF or 31 Mar 2026 | 48 months or 1200.0 TTAF | March 30, 2022 | 18767.6 TTAF | |
| Cargo Hook 528-028-00 36 | Green | | over 2 years | 31 Mar 2026 | 60 months | March 04, 2021 | | |
| 48 Month Airframe Inspection MSM 05-23-02 | Green | | almost 3 years | 28 Jul 2026 | 48 months | July 28, 2022 | 18886.6 TTAF | |
| 1000HR/48 Month Fuel Filter. (Lebozec) MSM 05-25-00, 28-20 | Green | TTAF: 19644.4 | 444.9 TTAF or almost 3 years | 20089.3 TTAF or 31 Jul 2026 | 48 months or 1200.0 TTAF | July 29, 2022 | 18889.3 TTAF | |
| 1200H/48 MONTH MGB OIL CHANGE MSM 05-23-00 63-20 | Green | TTAF: 19644.4 | 444.9 TTAF or almost 3 years | 20089.3 TTAF or 31 Jul 2026 | 48 months or 1200.0 TTAF | July 29, 2022 | 18889.3 TTAF | |
| 1200HR/48 Month Hydraulic Oil & Filter Replacement MSM 05-23-00, 29-10 | Green | TTAF: 19644.4 | 444.9 TTAF or almost 3 years | 20089.3 TTAF or 31 Jul 2026 | 48 months or 1200.0 TTAF | July 29, 2022 | 18889.3 TTAF | |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|--------|---------------|-------------------------------|-----------------------------|---------------------------|--------------------|--------------------|----------------------|
| 3000HR/48 Month Hydraulic system Strainer Cleaning MSM 05-23-00, 29-00 | Green | TTAF: 19644.4 | 2330.1 TTAF or about 3 years | 21974.5 TTAF or 30 Sep 2026 | 48 months or 3000.0 TTAF | September 09, 2022 | 18974.5 TTAF | |
| Hydraulic Hoses All NSN | Green | | about 3 years | 31 Oct 2026 | 120 months | October 10, 2016 | | |
| 72 MONTH RETIREMENT. Fire Extinguisher (Amerex) A620T G18295652 | Green | | over 3 years | 31 Jan 2027 | 72 months | January 01, 2021 | | |
| ELT Battery Replacement (Artex ME406) 453-6604 (ELT Battery (Artex ME406), 453-6604, SN: 188-09063) | Green | | over 3 years | 02 Feb 2027 | 72 months | February 02, 2021 | | |
| 72 MONTH Mast Corrosion Inspection | Green | | over 3 years | 28 Feb 2027 | 72 months | February 09, 2021 | | |
| 1200HR/48 Month Airframe Inspection MSM 05-23-00 (Gearbox and Hydraulic Filter tracked as separate items) | Green | TTAF: 19644.4 | 1000.8 TTAF or almost 4 years | 20645.2 TTAF or 31 Jul 2027 | 48 months or 1200.0 TTAF | July 03, 2023 | 19445.2 TTAF | |
| Fuel Hoses All NSN | Green | | over 4 years | 31 May 2028 | 120 months | May 26, 2018 | | |
| 5400HR/144M Landing Gear Dampener Inspection (350A75-2050-06, Landing Gear dampers X2, SN: MNPC-321 & 040416-1) | Green | TTAF: 19644.4 | 2959.5 TTAF or almost 6 years | 22603.9 TTAF or 07 Aug 2029 | 144 months or 5400.0 TTAF | August 07, 2017 | 17203.9 TTAF | |
| 2400H/72 MONTH MGB Oil Temp Warning System Check MSM 05-25-00, 63-40 (350A32-0300-05, MGB Bevel Reduction, SN: M1040) | Green | TTAF: 19644.4 | 2352.2 TTAF or almost 6 years | 21996.6 TTAF or 31 Aug 2029 | 72 months or 2400.0 TTAF | August 26, 2023 | 19596.6 TTAF | |
| 5400HR/144 Month Landing Gear Damper MSM 05-25-00, 32-00 (SN:040416-1) | Green | TTAF: 19644.4 | 2959.5 TTAF or about 6 years | 22603.9 TTAF or 31 Oct 2029 | 144 months or 5400.0 TTAF | October 26, 2017 | 17203.9 TTAF | |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|--------|---------------|----------------|--------------|-------------|--------------------|--------------------|----------------------|
| 144M DETAILED CHECK OF FLIGHTCONTROLS MSM 05-25-00, 67-00 | Green | | over 6 years | 30 Apr 2030 | 144 months | April 16, 2018 | | |
| 144M MGB CORROSION CHECK MSM 05-25-00 60-00 | Green | | over 6 years | 31 May 2030 | 144 months | May 02, 2018 | | |
| 144Month P2 Pipe Replacement MSM 05-25-00, 21-21 | Green | | over 6 years | 31 May 2030 | 144 months | May 26, 2018 | | |
| 144 Month Structure Inpsection MSM 05-25-00, 53-00 | Green | | over 6 years | 31 May 2030 | 144 months | May 26, 2018 | | |
| 144 Month Vertical Fin Support Inspection MSM 05-25-00, 55-20 | Green | | over 6 years | 31 May 2030 | 144 months | May 26, 2018 | | |
| 144M TGB Corrosion Check MSM 05-25-00 | Green | | over 6 years | 31 May 2030 | 144 months | May 11, 2018 | | |
| MGB Bevel Reduction 350A32-0300-05 M1040 | Green | | over 18 years | 31 May 2042 | 288 months | May 02, 2018 | | |
| MGB Oil Pump 350A32-0400-00 M1081 | Green | | over 18 years | 31 May 2042 | 288 months | May 02, 2018 | | |
| 1000HR Starter Generator overhaul (200SGL152Q-1 Starter Generator, 200A, SN: S00005) | Green | TTAF: 19644.4 | 218.1 TTAF | 19862.5 TTAF | 1000.0 TTAF | June 21, 2022 | 18862.5 TTAF | |
| 100H AIRBUS COWLING MAINTENANCE STEPS STC SH97-36 | Green | TTAF: 19644.4 | 52.2 TTAF | 19696.6 TTAF | 100.0 TTAF | August 26, 2023 | 19596.6 TTAF | |
| 100H CHINOOK VERTICAL REFERENCE WINDOW STC SH00-43 | Green | TTAF: 19644.4 | 52.2 TTAF | 19696.6 TTAF | 100.0 TTAF | August 26, 2023 | 19596.6 TTAF | |
| 100H HELILYNX OIL VENT LINE RE-ROUTING STC SH04-4 | Green | TTAF: 19644.4 | 52.2 TTAF | 19696.6 TTAF | 100.0 TTAF | August 26, 2023 | 19596.6 TTAF | |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|------------------------|-----------------------|------------------------|------------------------|--------------------|-----------------------|----------------------|
| 100H LTS101 ENGINE Delta P-check LTS101-2.1 MM 72-00-00 Table 4.5 (SB LTS101-71-00-0251) (LTS101-700D-2, Turbine Engine, SN: LE-49018C) | Green | TTAF: 19644.4 | 52.2 TTAF | 19696.6 TTAF | 100.0 TTAF | August 26, 2023 | 19596.6 TTAF | |
| 100HR Airframe Inspection (05-25-00) MSM 05-25-00 | Green | TTAF: 19644.4 | 52.2 TTAF | 19696.6 TTAF | 100.0 TTAF | August 26, 2023 | 19596.6 TTAF | |
| 120000 TC MR Mast Retirement (350A37-1290-04, Main Rotor Shaft, SN: M2871) | Green | TORQUE CYCLES: 98983.0 | 53512.6 TORQUE CYCLES | 152495.6 TORQUE CYCLES | 120000.0 TORQUE CYCLES | April 21, 2023 | 32495.6 TORQUE CYCLES | |
| 12500 Hr TR Gearbox Bevel Wheel Retirement (350A33-1001-21, T/R Gbox Bevel Wheel, SN: L13024) | Green | TTAF: 19644.4 | 10059.5 TTAF | 29703.9 TTAF | 12500.0 TTAF | April 20, 2023 | 17203.9 TTAF | |
| 13300HR Splined Shaft Retirement FX2 Specific (350A35-1001-22FX, Splined Shaft (Heli Lynx), SN: 25) | Green | TTAF: 19644.4 | 6389.0 TTAF | 26033.4 TTAF | 13300.0 TTAF | April 21, 2023 | 12733.4 TTAF | |
| 150H LTS101 ENGINE INSPECTION LTS101-2.1 MM 72-00-00 Table 5 (LTS101-700D-2, Turbine Engine, SN: LE-49018C) | Green | TTAF: 19644.4 | 102.2 TTAF | 19746.6 TTAF | 150.0 TTAF | August 26, 2023 | 19596.6 TTAF | |
| 150HR Airframe Inspection MSM 05-21-01 | Green | TTAF: 19644.4 | 102.2 TTAF | 19746.6 TTAF | 150.0 TTAF | August 26, 2023 | 19596.6 TTAF | |
| 150HR FDC INSPECTION STC SR00811SE/SR01049SE (1350A22-1 FDC Inlet Filter, SN: 00015) | Green | TTAF: 19644.4 | 102.2 TTAF | 19746.6 TTAF | 150.0 TTAF | August 26, 2023 | 19596.6 TTAF | |
| 1800HR Servo Overhaul (SN: BJ270) Fore/Aft (AC67246, M/R Fore/Aft Servo, SN: BJ270) | Green | TTAF: 19644.4 | 1600.8 TTAF | 21245.2 TTAF | 1800.0 TTAF | July 03, 2023 | 19445.2 TTAF | |
| 1800HR Servo Overhaul (SN: DC491) (AC67244, M/R Lateral Servo (Dunlop), SN: DC491) | Green | TTAF: 19644.4 | 1272.0 TTAF | 20916.4 TTAF | 1800.0 TTAF | February 06, 2023 | 19116.4 TTAF | |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|--------|---------------|----------------|--------------|--------------|--------------------|--------------------|----------------------|
| 1800HR Servo Overhaul (SN: NP223) (AC67244, M/R Lateral Servo (Dunlop), SN: NP223) | Green | TTAF: 19644.4 | 1600.8 TTAF | 21245.2 TTAF | 1800.0 TTAF | July 03, 2023 | 19445.2 TTAF | |
| 20000 HR MGB Bevel Gear Retirement (350A32-3173-20, MGB Bevel Gear/ Pinion, SN: L862) | Green | TTAF: 19644.4 | 17559.5 TTAF | 37203.9 TTAF | 20000.0 TTAF | April 20, 2023 | 17203.9 TTAF | |
| 20000 HR MGB Bevel Wheel Retirement (350A32-3166-20, MGB Bevel Wheel, SN: L741) | Green | TTAF: 19644.4 | 17559.5 TTAF | 37203.9 TTAF | 20000.0 TTAF | April 20, 2023 | 17203.9 TTAF | |
| 20000 HR MGB Bottom Casing Retirement (350A32-3119-05, MGB Bottom Housing, SN: MAP5725) | Green | TTAF: 19644.4 | 7009.4 TTAF | 26653.8 TTAF | 20000.0 TTAF | April 20, 2023 | 6653.8 TTAF | |
| 20000 HR MGB Planetary Gear Retirement (350A32-1082-03, Planet Gear, SN: L31453) | Green | TTAF: 19644.4 | 15521.1 TTAF | 35165.5 TTAF | 20000.0 TTAF | April 20, 2023 | 15165.5 TTAF | |
| 20000 HR MGB Planetary Gear Retirement (1) (350A32-1082-03, Planet Gear, SN: L31372) | Green | TTAF: 19644.4 | 15521.1 TTAF | 35165.5 TTAF | 20000.0 TTAF | April 20, 2023 | 15165.5 TTAF | |
| 20000 HR MGB Planetary Gear Retirement (2) (350A32-1082-03, Planet Gear, SN: L31467) | Green | TTAF: 19644.4 | 15521.1 TTAF | 35165.5 TTAF | 20000.0 TTAF | April 20, 2023 | 15165.5 TTAF | |
| 20000 HR MGB Planetary Gear Retirement (3) (350A32-1082-03, Planet Gear, SN: L31976) | Green | TTAF: 19644.4 | 15521.1 TTAF | 35165.5 TTAF | 20000.0 TTAF | April 20, 2023 | 15165.5 TTAF | |
| 20000 HR MGB Planetary Gear Retirement (4) (350A32-1082-03, Planet Gear, SN: L31377) | Green | TTAF: 19644.4 | 15521.1 TTAF | 35165.5 TTAF | 20000.0 TTAF | April 20, 2023 | 15165.5 TTAF | |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|--------|---------------|----------------|--------------|---------------|--------------------|--------------------|----------------------|
| 20000 HR MR Blade Retirement (355A11-0030-00 (Yel), Main Rotor Blade, SN: 22169) | Green | TTAF: 19644.4 | 11922.7 TTAF | 31567.1 TTAF | 20000.0 TTAF | April 21, 2023 | 11567.1 TTAF | |
| 20000 HR MR Blade Retirement (355A11-0030-04 (Blu), Main Rotor Blade, SN: 30498) | Green | TTAF: 19644.4 | 13226.2 TTAF | 32870.6 TTAF | 20000.0 TTAF | April 21, 2023 | 12870.6 TTAF | |
| 20000 HR MR Blade Retirement (355A11-0030-00 (Red), Main Rotor Blade, SN: 22144) | Green | TTAF: 19644.4 | 11634.1 TTAF | 31278.5 TTAF | 20000.0 TTAF | April 21, 2023 | 11278.5 TTAF | |
| 20000HR MR Mast Retirement (350A37-1290-04, Main Rotor Shaft, SN: M2871) | Green | TTAF: 19644.4 | 1371.1 TTAF | 21015.5 TTAF | 20000.0 TTAF | April 21, 2023 | 1015.5 TTAF | |
| 20000HR Retirement of TR Gearbox Housing (350A33-1090-01, T/R GBOX Casing/ Housing, SN: DA262) | Yellow | TTAF: 19644.4 | 398.6 TTAF | 20043.0 TTAF | 20000.0 TTAF | January 06, 2023 | 43.0 TTAF | |
| 20000 HR TR Gearbox Control Lever Retirement (350A33-1526-00, Tail Rotor Control Lever., SN: MA68930) | Green | TTAF: 19644.4 | 15917.9 TTAF | 35562.3 TTAF | 20000.0 TTAF | April 20, 2023 | 15562.3 TTAF | |
| 2400HR Boost Pump Brush Inspection (P94B12-209) MSM 05-25-00, 28-20 & CMM 28-19-04 (SN:H29433) | Green | TTAF: 19644.4 | 1108.3 TTAF | 20752.7 TTAF | 2400.0 TTAF | | 18352.7 TTAF | |
| 24 Month Battery Replacement 24 Month Battery Replacement (M803 Davtron Clock, SN: M803 ICA) | Green | | | | NON RECURRING | January 19, 2022 | | |
| 2700HR TR Gearbox Overhaul FX2 Only (350A33-0200-05, T/R GBOX ASSY, SN: MA0035) | Yellow | TTAF: 19644.4 | 259.5 TTAF | 19903.9 TTAF | 2700.0 TTAF | April 20, 2023 | 17203.9 TTAF | |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------------|----------------|--------------|-------------|--------------------|--------------------|----------------------|
| 3000HR Epicyclic Overhaul (350A32-0100-10, Epicyclic Assy, SN: M425) | Green | TTAF: 19644.4 | 1719.5 TTAF | 21363.9 TTAF | 3000.0 TTAF | April 20, 2023 | 18363.9 TTAF | |
| 3000HR Main Rotor Attach Bolt Retirement (1) (350A37-1245-20, Main Rotor Attach Bolt, SN: 126649) | Green | TTAF: 19644.4 | 1719.5 TTAF | 21363.9 TTAF | 3000.0 TTAF | April 21, 2023 | 18363.9 TTAF | |
| 3000HR Main Rotor Attach Bolt Retirement (10) (350A37-1245-20, Main Rotor Attach Bolt, SN: 126762) | Green | TTAF: 19644.4 | 1719.5 TTAF | 21363.9 TTAF | 3000.0 TTAF | April 21, 2023 | 18363.9 TTAF | |
| 3000HR Main Rotor Attach Bolt Retirement (11) (350A37-1245-20, Main Rotor Attach Bolt, SN: 126814) | Green | TTAF: 19644.4 | 1719.5 TTAF | 21363.9 TTAF | 3000.0 TTAF | April 21, 2023 | 18363.9 TTAF | |
| 3000HR Main Rotor Attach Bolt Retirement (12) (350A37-1244-20, Main Rotor Attach Bolt, SN: 13203) | Green | TTAF: 19644.4 | 1719.5 TTAF | 21363.9 TTAF | 3000.0 TTAF | April 21, 2023 | 18363.9 TTAF | |
| 3000HR Main Rotor Attach Bolt Retirement (2) (350A37-1244-20, Main Rotor Attach Bolt, SN: 133159) | Green | TTAF: 19644.4 | 1719.5 TTAF | 21363.9 TTAF | 3000.0 TTAF | April 21, 2023 | 18363.9 TTAF | |
| 3000HR Main Rotor Attach Bolt Retirement (3) (350A37-1244-20, Main Rotor Attach Bolt, SN: 133168) | Green | TTAF: 19644.4 | 1719.5 TTAF | 21363.9 TTAF | 3000.0 TTAF | April 21, 2023 | 18363.9 TTAF | |
| 3000HR Main Rotor Attach Bolt Retirement (4) (350A37-1245-20, Main Rotor Attach Bolt, SN: 126408) | Green | TTAF: 19644.4 | 1719.5 TTAF | 21363.9 TTAF | 3000.0 TTAF | April 21, 2023 | 18363.9 TTAF | |
| 3000HR Main Rotor Attach Bolt Retirement (5) (350A37-1244-20, Main Rotor Attach Bolt, SN: 133185) | Green | TTAF: 19644.4 | 1719.5 TTAF | 21363.9 TTAF | 3000.0 TTAF | April 21, 2023 | 18363.9 TTAF | |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------------|----------------|--------------|-------------|--------------------|--------------------|----------------------|
| 3000HR Main Rotor Attach Bolt Retirement (6) (350A37-1245-20, Main Rotor Attach Bolt, SN: 122821) | Green | TTAF: 19644.4 | 1719.5 TTAF | 21363.9 TTAF | 3000.0 TTAF | April 21, 2023 | 18363.9 TTAF | |
| 3000HR Main Rotor Attach Bolt Retirement (7) (350A37-1244-20, Main Rotor Attach Bolt, SN: 133363) | Green | TTAF: 19644.4 | 1719.5 TTAF | 21363.9 TTAF | 3000.0 TTAF | April 21, 2023 | 18363.9 TTAF | |
| 3000HR Main Rotor Attach Bolt Retirement (8) (350A37-1245-20, Main Rotor Attach Bolt, SN: 122802) | Green | TTAF: 19644.4 | 1719.5 TTAF | 21363.9 TTAF | 3000.0 TTAF | April 21, 2023 | 18363.9 TTAF | |
| 3000HR Main Rotor Attach Bolt Retirement (9) (350A37-1244-20, Main Rotor Attach Bolt, SN: 133378) | Green | TTAF: 19644.4 | 1719.5 TTAF | 21363.9 TTAF | 3000.0 TTAF | April 21, 2023 | 18363.9 TTAF | |
| 3000HR Starflex Retirement (350A31-1918-00, Starflex, SN: M5351) | Green | TTAF: 19644.4 | 678.7 TTAF | 20323.1 TTAF | 3000.0 TTAF | April 20, 2023 | 17323.1 TTAF | |
| 3000HR Thrust Bolt Retirement (1) (350A31-1854-21 Thrust Bolt, SN: 84575) | Green | TTAF: 19644.4 | 2026.4 TTAF | 21670.8 TTAF | 3000.0 TTAF | April 20, 2023 | 18670.8 TTAF | |
| 3000HR Thrust Bolt Retirement (2) (350A31-1854-21 Thrust Bolt, SN: 84355) | Green | TTAF: 19644.4 | 2026.4 TTAF | 21670.8 TTAF | 3000.0 TTAF | April 20, 2023 | 18670.8 TTAF | |
| 3000HR Thrust Bolt Retirement (3) (350A31-1854-21 Thrust Bolt, SN: 87162) | Green | TTAF: 19644.4 | 2026.4 TTAF | 21670.8 TTAF | 3000.0 TTAF | April 20, 2023 | 18670.8 TTAF | |
| 3000HR Thrust Bolt Retirement (4) (350A31-1854-21 Thrust Bolt, SN: 87163) | Green | TTAF: 19644.4 | 2026.4 TTAF | 21670.8 TTAF | 3000.0 TTAF | April 20, 2023 | 18670.8 TTAF | |
| 3000HR Thrust Bolt Retirement (5) (350A31-1854-21 Thrust Bolt, SN: 87167) | Green | TTAF: 19644.4 | 2026.4 TTAF | 21670.8 TTAF | 3000.0 TTAF | April 20, 2023 | 18670.8 TTAF | |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------------|----------------|--------------|-------------|--------------------|--------------------|----------------------|
| 3000HR Thrust Bolt Retirement (6) (350A31-1854-21 Thrust Bolt, SN: 84494) | Green | TTAF: 19644.4 | 2026.4 TTAF | 21670.8 TTAF | 3000.0 TTAF | April 20, 2023 | 18670.8 TTAF | |
| 3000 HR TR Pitch Change spider Bearing retirement (704A33-651-210, T/R Spider Pitch Change Bearing, SN: NR6871) | Green | TTAF: 19644.4 | 2629.6 TTAF | 22274.0 TTAF | 3000.0 TTAF | May 11, 2023 | 19274.0 TTAF | |
| 300H HELILYNX DEICING FUEL FILTER STC SH07-31 | Yellow | TTAF: 19644.4 | 55.9 TTAF | 19700.3 TTAF | 300.0 TTAF | June 15, 2023 | 19400.3 TTAF | |
| 300H LTS101 ENGINE INSPECTION LTS101-2.1 MM 72-00-00 Table 7 (LTS101-700D-2, Turbine Engine, SN: LE-49018C) | Yellow | TTAF: 19644.4 | 55.9 TTAF | 19700.3 TTAF | 300.0 TTAF | June 15, 2023 | 19400.3 TTAF | |
| 300 HR Swashplate Guide and Swivel Bearing Inspection MSM 05-25-00, 62-30 | Yellow | TTAF: 19644.4 | 55.9 TTAF | 19700.3 TTAF | 300.0 TTAF | June 15, 2023 | 19400.3 TTAF | |
| 300H STARTER GENERATOR BRUSHINSPECTION ASL 350FX-05-07 Page 15 or SOLOY M&OM SUPPLEMENT 05-20-00 TABLE3 (200SGL152Q-1 Starter Generator, 200A, SN: S00005) | Green | TTAF: 19644.4 | 252.2 TTAF | 19896.6 TTAF | 300.0 TTAF | August 26, 2023 | 19596.6 TTAF | |
| 3500HR Overhaul of MGB (Bevel Reduction Gearbox) (350A32-0300-05, MGB Bevel Reduction, SN: M1040) | Green | TTAF: 19644.4 | 1059.5 TTAF | 20703.9 TTAF | 3500.0 TTAF | April 20, 2023 | 17203.9 TTAF | |
| 3500HR Overhaul of MGB Oil Pump (350A32-0400-00, MGB Oil Pump, SN: M1081) | Green | TTAF: 19644.4 | 1059.5 TTAF | 20703.9 TTAF | 3500.0 TTAF | April 20, 2023 | 17203.9 TTAF | |
| 3600 HR TR Drive shaft Bearing Retirement X6 (704A33-651-181 (593404), BEARING, T/R DRIVESHAFT (X6), SN: NSN) | Green | TTAF: 19644.4 | 1520.6 TTAF | 21165.0 TTAF | 3600.0 TTAF | April 20, 2023 | 17565.0 TTAF | |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|--------|------------------------|-----------------------|------------------------|-----------------------|--------------------|-----------------------|----------------------|
| 4000HR TR Blade Replacement (355A12-0050-14, Tail Rotor Blade, SN: 24051) | Green | TTAF: 19644.4 | 2245.8 TTAF | 21890.2 TTAF | 4000.0 TTAF | January 06, 2023 | 17890.2 TTAF | |
| 4100 HR TR Gearbox Pinion Gear Retirement (350A33-1000-21, T/R GBOX Bevel Gear, SN: L14562) | Green | TTAF: 19644.4 | 1659.5 TTAF | 21303.9 TTAF | 4100.0 TTAF | April 20, 2023 | 17203.9 TTAF | |
| 4200H/60000TC MGB SUSPENSION CROSSBAR INSPECTION AS350B2 ALS 04-20-00 63-30 | Green | TORQUE CYCLES: 98983.0 | 48489.0 TORQUE CYCLES | 147472.0 TORQUE CYCLES | 60000.0 TORQUE CYCLES | | 87472.0 TORQUE CYCLES | |
| 4500HR FDC Filter Retirement PN: 1350A22-1 STC: SR00811SE/SR01049SE (1350A22-1 FDC Inlet Filter, SN: 00015) | Green | TTAF: 19644.4 | 1082.6 TTAF | 20727.0 TTAF | 4500.0 TTAF | April 20, 2023 | 16227.0 TTAF | |
| 5000 HR Dampening Capacitor Retirement (366A54-1088-00, Dampening Capacitor 2 (Heli Lynx), SN: WC0171) | Green | TTAF: 19644.4 | 1688.9 TTAF | 21333.3 TTAF | 5000.0 TTAF | April 21, 2023 | 16333.3 TTAF | |
| 5000 HR Dampening Capacitor Retirement (350A54-1091-00, Dampening Capacitor (Heli Lynx), SN: N/A) | Green | TTAF: 19644.4 | 4330.1 TTAF | 23974.5 TTAF | 5000.0 TTAF | April 21, 2023 | 18974.5 TTAF | |
| 50 HR ENG Power Assurance Check. Eiji accidentally deleted. | Green | TTAF: 19644.4 | 21.6 TTAF | 19666.0 TTAF | 50.0 TTAF | September 02, 2023 | 19616.0 TTAF | |
| 5400HR Landing Gear inspection MSM 05-25-00, 32-13 | Green | TTAF: 19644.4 | 2959.5 TTAF | 22603.9 TTAF | 5400.0 TTAF | | 17203.9 TTAF | |
| 600H/24M HELI-LYNX STC Inspection STC SH06-5 & SH15-30 | Green | TTAF: 19644.4 | 400.8 TTAF | 20045.2 TTAF | 600.0 TTAF | July 03, 2023 | 19445.2 TTAF | |
| 600H LTS101 ENGINE INSPECTION LTS101-2.1 MM 72-00-00 Table 7 (LTS101-700D-2, Turbine Engine, SN: LE-49018C) | Green | TTAF: 19644.4 | 229.6 TTAF | 19874.0 TTAF | 600.0 TTAF | May 11, 2023 | 19274.0 TTAF | |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|--------|---------------|----------------|--------------|--------------|--------------------|--------------------|----------------------|
| 600HR Airframe Inspection MSM 05-22-01 | Green | TTAF: 19644.4 | 400.8 TTAF | 20045.2 TTAF | 600.0 TTAF | July 03, 2023 | 19445.2 TTAF | |
| 6600HR Sleeve replacement (L1) (350A31-1850-02, Lower Sleeve, SN: M16426) | Green | TTAF: 19644.4 | 6229.6 TTAF | 25874.0 TTAF | 6600.0 TTAF | May 11, 2023 | 19274.0 TTAF | |
| 6600HR Sleeve replacement (L2) (350A31-1850-02, Lower Sleeve, SN: M16428) | Green | TTAF: 19644.4 | 6229.6 TTAF | 25874.0 TTAF | 6600.0 TTAF | May 11, 2023 | 19274.0 TTAF | |
| 6600HR Sleeve replacement (L3) (350A31-1850-02, Lower Sleeve, SN: M16431) | Green | TTAF: 19644.4 | 6229.6 TTAF | 25874.0 TTAF | 6600.0 TTAF | May 11, 2023 | 19274.0 TTAF | |
| 6600HR Sleeve replacement (U1) (350A31-1850-03, Upper Sleeve, SN: M15638) | Green | TTAF: 19644.4 | 6229.6 TTAF | 25874.0 TTAF | 6600.0 TTAF | May 11, 2023 | 19274.0 TTAF | |
| 6600HR Sleeve replacement (U2) (350A31-1850-03, Upper Sleeve, SN: M15620) | Green | TTAF: 19644.4 | 6229.6 TTAF | 25874.0 TTAF | 6600.0 TTAF | May 11, 2023 | 19274.0 TTAF | |
| 6600HR Sleeve replacement (U3) (350A31-1850-03, Upper Sleeve, SN: M15624) | Green | TTAF: 19644.4 | 6229.6 TTAF | 25874.0 TTAF | 6600.0 TTAF | May 11, 2023 | 19274.0 TTAF | |
| 660HR AD 2023-0044 (28 Feb 2023) - MGB Borescope inspection Applicable to C-GHCT 350A32-1082-03 Planetary gear bearing currently installed | Green | TTAF: 19644.4 | 134.2 TTAF | 19778.6 TTAF | 600.0 TTAF | March 03, 2023 | 19178.6 TTAF | |
| 80000 HR Pitch Horn Retirement (1) (350A31-1877-02X, Blade Horn, SN: M2221) | Green | TTAF: 19644.4 | 60355.6 TTAF | 80000.0 TTAF | 80000.0 TTAF | April 20, 2023 | 0.0 TTAF | |
| 80000 HR Pitch Horn Retirement (2) (350A31-1877-02X, Blade Horn, SN: M2049) | Green | TTAF: 19644.4 | 60355.6 TTAF | 80000.0 TTAF | 80000.0 TTAF | April 20, 2023 | 0.0 TTAF | |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|------------------------|-----------------------|------------------------|-----------------------|--------------------|-----------------------|---|
| 80000 HR Pitch Horn Retirement (3) (350A31-1877-02X, Blade Horn, SN: M2119) | Green | TTAF: 19644.4 | 60355.6 TTAF | 80000.0 TTAF | 80000.0 TTAF | April 20, 2023 | 0.0 TTAF | |
| 9000 HR TR Driveshaft Aft Shaft retirement (350A34-1011-05 T/R Driveshaft Aft Shaft, SN: M2385) | Green | TTAF: 19644.4 | 2632.8 TTAF | 22277.2 TTAF | 9000.0 TTAF | April 20, 2023 | 13277.2 TTAF | |
| 93700 TC MGB Bottom Casing Retirement Torque Cycles/Torque Events (350A32-3119-05, MGB Bottom Housing, SN: MAP5725) | Green | TORQUE CYCLES: 98983.0 | 18888.0 TORQUE CYCLES | 117871.0 TORQUE CYCLES | 93700.0 TORQUE CYCLES | April 20, 2023 | 24171.0 TORQUE CYCLES | |
| AD 1997-147-072(A)R1 - TAIL BOOM ATTACHMENT SCREWS - (01.00.46) TAIL BOOM ATTACHMENT SCREWS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | February 21, 2002 | 9299.7 TTAF | C/W - GEMINI HELI / M368661 |
| AD 1999-085-076(A)R3 - TAIL ROTOR HUB PITCH CHANGE PLATE BEARING - (ASB 05.00.29) TAIL ROTOR HUB PITCH CHANGE PLATE BEARING | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | April 16, 2002 | 9305.5 TTAF | N/A MOD 07-6551 C/W ON SPIDER ASSY PN - GEMINI HELI / M368661 |
| AD 2000-268-078(A) - TAIL ROTOR HUB PITCH CHANGE PLATE BEARING - (ASB 05.00.29) TAIL ROTOR HUB PITCH CHANGE PLATE BEARING | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | November 30, 2000 | 8856.3 TTAF | N/A MOD 07-6551 C/W ON SPIDER ASSY PN - GEMINI HELI / M368661 |
| AD 2000-302(A) - ATA 28 - FUEL - FERRY FUEL TANKS ELECTRICAL BONDING - MODIFICATION - (79.00.11) ATA 28 - FUEL - FERRY FUEL TANKS ELECTRICAL BONDING - MODIFICATION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | November 30, 2000 | 8856.3 TTAF | N/A BY A/C CONFIGURATION - FERRY FUEL TANKS NOT INSTALLED - GEMINI HELI / M368661 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|--|
| AD 2001-074-081(A) - T/R HUB PITCH CHANGE BEARINGS - (01.00.48) T/R HUB PITCH CHANGE BEARINGS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | April 02, 2001 | 8910.7 TTAF | C/W - CONFIRMED BY GEMINI HELI / M368661 |
| AD 2001-22-07 - REPLACEMENT OF FUEL MANIFOLDS REPLACEMENT OF FUEL MANIFOLDS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | August 20, 2015 | 9292.4 TTAF | C/W, NDF - OPSMOBIL |
| AD 2001-557-086(A)R3 - INSPECTION OF MAIN ROTOR STARFLEX STAR - (05.00.38R2, 62.00.24) INSPECTION OF MAIN ROTOR STARFLEX STAR | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | July 15, 2018 | 17323.1 TTAF | N/A BY P/N, DOM, AND MOD - ARIBUS HELICOPTERS F0210 |
| AD 2002-03-09R1 - IMPELLER BACK FACE AREA CRACKS - 101-72-30-0186 IMPELLER BACK FACE AREA CRACKS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | November 10, 2005 | | P/C/W on April 4, 2002 - GEMINI HELI / M368661 |
| AD 2002-537-094(A) - EUROCOPTER AS 350 SERIES - MOBILE COWLING SEALS - (ASB 53.00.31) EUROCOPTER AS 350 SERIES - MOBILE COWLING SEALS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | January 17, 2003 | 9749.6 TTAF | P/C/W IAW ASB 53.00.31 ON DEC 12, 2002 - GEMINI HELI / M368661 |
| ad 2003-099(A) - MAIN AND TAIL TRW SAMM SERVOCONTROL - (01.00.52) MAIN AND TAIL TRW SAMM SERVOCONTROL | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 19, 2003 | 9768.7 TTAF | N/A BY P/N AC67 INSTALLED - GEMINI HELI / M368661 |
| ad 2003-406(A) - EUROCOPTER AS 350 - ROTOR FLIGHT CONTROLS - (67.00.27) EUROCOPTER AS 350 - ROTOR FLIGHT CONTROLS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | October 29, 2003 | 10297.6 TTAF | N/A NOT INSTALLED - AMO 75-99 M368661 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|---|
| AD 2006-0055-E - ROTOR FLIGHT CONTROLS - MAIN SERVO-CONTROLS - (SB 05.00.51) ROTOR FLIGHT CONTROLS - MAIN SERVO-CONTROLS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | March 07, 2006 | 11626.4 TTAF | C/W IAW ASB 05.00.51, NO FAULTS FOUND - GEMINI HELI / WADE KIDD |
| AD 2006-0098 - EQUIPMENT / FURNISHINGS - HOIST HOOK - (01.00.54) EQUIPMENT / FURNISHINGS - HOIST HOOK | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 26, 2006 | 11726.1 TTAF | N/A BY A/C CONFIGURATION - HOIST NOT INSTALLED AT THIS TIME - Christian Dallaire ACA 1 AMO 75-99 |
| AD 2006-0164 - EQUIPMENT/FURNISHINGS - UNTIMELY FIRING OF SQUIBS ON GOODRICH ELECTRIC HOISTS - (25.00.94) EQUIPMENT/FURNISHINGS - UNTIMELY FIRING OF SQUIBS ON GOODRICH ELECTRIC HOISTS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | June 28, 2006 | 11830.4 TTAF | N/A BY A/C CONFIGURATION - ELECTRIC HOIST NOT INSTALLED AT THIS TIME |
| AD 2006-0249 - SLIDING DOOR - WEAR ON ROLLERS AND RAILS - (FAA 2003-02-05 / 05.00.41) SLIDING DOOR - WEAR ON ROLLERS AND RAILS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | October 12, 2006 | 12105.7 TTAF | N/A BY A/C CONFIGURATION - SLIDING DOOR NOT INSTALLED AT THIS TIME - Christian Dallaire ACA 1 AMO 75-99 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|--|
| AD 2006-0273 - FUSELAGE - RH CABIN VIBRATION DAMPER & BLADE - INSPECTION / REPLACEMENT / MODIFICATION - (05.00.48) FUSELAGE - RH CABIN VIBRATION DAMPER & BLADE - INSPECTION / REPLACEMENT / MODIFICATION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | October 12, 2006 | 12105.7 TTAF | N/A BY A/C CONFIGURATION - AUTO PILOT NOT INSTALLED AT THIS TIME - Christian Dallaire ACA 1 AMO 75-99 |
| AD 2006-11-17 - TO PREVENT RESTRICTING FULL LATERAL MOVEMENT OF THE CYCLIC CONTROL - (GA107-7) TO PREVENT RESTRICTING FULL LATERAL MOVEMENT OF THE CYCLIC CONTROL | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | June 28, 2006 | 11830.4 TTAF | N/A BY A/C CONFIGURATION - GENEVA AVIATION CONSOLE NOT INSTALLED AT THIS TIME - Christian Dallaire ACA 1 AMO 75-99 |
| AD 2007-0139-E - FUSELAGE - CENTER CROSS-MEMBER UNDER THE CABIN FLOOR - INSPECTION / MODIFICATION. - (53.00.37) FUSELAGE - CENTER CROSS-MEMBER UNDER THE CABIN FLOOR - INSPECTION / MODIFICATION. | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 16, 2007 | 12231.9 TTAF | C/W IAW ASB 53-37, CROSSMEMBERS ARE NOT PRESENT AND NO CRACKS FOUND - Christian Dallaire ACA 1 AMO 75-99 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|--|
| AD 2007-0141-E - ROTOR FLIGHT CONTROLS - MAIN & TAIL ROTORS SERVO-CONTROLS INSPECTION / REPLACEMENT. - (01.00.58) ROTOR FLIGHT CONTROLS - MAIN & TAIL ROTORS SERVO-CONTROLS INSPECTION / REPLACEMENT. | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 22, 2007 | 12244.6 TTAF | N/A BY P/N AC67 INSTALL ED - Christian Dallaire ACA 1 AMO 75-99 |
| AD 2007-0236 - DOORS - SLIDING DOOR REAR ROLLER SUPPORT SHAFT AND REAR FITTING INSPECTION/ REPLACEMENT - (52.00.30) DOORS - SLIDING DOOR REAR ROLLER SUPPORT SHAFT AND REAR FITTING INSPECTION/ REPLACEMENT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 22, 2007 | 12244.6 TTAF | N/A BY CONFIGURATION - SLIDING DOOR NOT INSTALL ED - ACA 2 AMO 75-99 |
| AD 2008-0044 - EQUIPMENT / FURNISHINGS - REAR BENCH SEAT AND SLIDING DOORS -LIMITATION / REMOVAL / MODIFICATION. - (25.00.70) EQUIPMENT / FURNISHINGS - REAR BENCH SEAT AND SLIDING DOORS -LIMITATION / REMOVAL / MODIFICATION. | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 14, 2008 | 12884.2 TTAF | C/W - Christian Dallaire ACA 1 AMO 75-99 |
| AD 2008-0121 - STABILIZERS – UPPER AND LOWER FIN ATTACHMENT FITTING -MODIFICATION - (55.00.16) STABILIZERS – UPPER AND LOWER FIN ATTACHMENT FITTING -MODIFICATION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | November 11, 2014 | 16860.0 TTAF | P/C/W ON DECEMBER 15, 2008 - OPSMOB IL AMO 75-99 ACA 13 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|---|
| AD 2008-0189 - ATA 25 - EQUIPMENT AND FURNISHINGS - EMERGENCY FLOTATION GEAR – REPLACEMENT. - (25.01.02) ATA 25 - EQUIPMENT AND FURNISHINGS - EMERGENCY FLOTATION GEAR – REPLACEMENT. | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | January 20, 2022 | 18678.0 TTAF | N/A BY A/C CONFIGURATION - FLOAST NOT INSTALLED - FHFA |
| AD 2008-0214-E - EQUIPMENT & FURNISHING - EMERGENCY FLOTATION GEAR - INSPECTION / LIMITATION / REPLACEMENT - (01.00.59) EQUIPMENT & FURNISHING - EMERGENCY FLOTATION GEAR - INSPECTION / LIMITATION / REPLACEMENT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | December 15, 2008 | 13268.7 TTAF | N/A BY A/C CONFIGURATION - FLOAST NOT INSTALLED - Greg Monk ACA 13 AMO 75-99 |
| AD 2009-0019 - ATA 67 - ROTORS FLIGHT CONTROL – COLLECTIVE PITCH LEVER LOCKING STUD – INSPECTION / REPAIR - (ASB 05.00.48) ATA 67 - ROTORS FLIGHT CONTROL – COLLECTIVE PITCH LEVER LOCKING STUD – INSPECTION / REPAIR | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | February 22, 2009 | 13277.2 TTAF | N/A COLLECTIVE LOCK SYSTEM NOT AFFECTED BY AD - Greg Monk ACA 13 AMO 75-99 |
| AD 2009-0027 - ATA 80 - ENGINE STARTING - STARTER-GENERATOR DAMPING ASSEMBLY ADJUSTMENT - (80.00.07) ATA 80 - ENGINE STARTING - STARTER-GENERATOR DAMPING ASSEMBLY ADJUSTMENT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | February 18, 2009 | 13385.0 TTAF | N/A, APC Started installed P/N 150SG11 7Q Not Affected - Greg Monk ACA 13 AMO 75-99 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|---|
| AD 2009-0030 - ATA 55 - STABILIZERS - UPPER AND LOWER FIN ATTACHEMENT FITTING - INSPECTION / MODIFICATION / REPLACEMENT - (55.00.16) ATA 55 - STABILIZERS - UPPER AND LOWER FIN ATTACHEMENT FITTING - INSPECTION / MODIFICATION / REPLACEMENT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | February 22, 2009 | 13277.2 TTAF | N/A BY AD 2008-0121 & MOD 3330 FOUND TO BE P/C/W - Greg Monk ACA 13 AMO 75-99 |
| AD 2009-0039 - ATA 64 - TAIL ROTOR - TAIL ROTOR BLADES SKIN - INSPECTION / REPAIR - (05.00.40) ATA 64 - TAIL ROTOR - TAIL ROTOR BLADES SKIN - INSPECTION / REPAIR | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | March 05, 2009 | 13385.0 TTAF | N/A BY T/R P/N 355A12-0050-14 INSTALLED - GEMINI HELI / M368661 |
| AD 2009-0122R1 - ATA 25 - EQUIPMENT / FURNISHING - LOAD RELEASE UNITS - INSPECTION / MODIFICATION / LIMITATION - (01.00.49) ATA 25 - EQUIPMENT / FURNISHING - LOAD RELEASE UNITS - INSPECTION / MODIFICATION / LIMITATION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | November 12, 2010 | 14171.3 TTAF | C/W on WO 2131 - ACA 21 AMO 75-99 |
| AD 2009-0251-E - ATA 26 - FIRE PROTECTION - PORTABLE FIRE EXTINGUISHERS - IDENTIFICATION / REPLACEMENT ATA 26 - FIRE PROTECTION - PORTABLE FIRE EXTINGUISHERS - IDENTIFICATION / REPLACEMENT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | March 15, 2021 | 18364.8 TTAF | N/A BY TYPE OF F/E NOT AFFECTED BY AD - FHATA |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|--|
| AD 2009-0262R1 - FIRE PROTECTION - HALON 1211 FIRE EXTINGUISHERS - IDENTIFICATION / REPLACEMENT - (SB 26-115) FIRE PROTECTION - HALON 1211 FIRE EXTINGUISHERS - IDENTIFICATION / REPLACEMENT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | March 15, 2021 | 18364.8 TTAF | N/A BY TYPE OF F/E NOT AFFECTED BY AD - FHTA |
| AD 2009-0277R1 - ATA 26 - FIRE PROTECTION – PORTABLE HALON 1211 FIRE EXTINGUISHERS – IDENTIFICATION / REPLACEMENT - (863520-26-001) ATA 26 - FIRE PROTECTION – PORTABLE HALON 1211 FIRE EXTINGUISHERS – IDENTIFICATION / REPLACEMENT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | March 15, 2021 | 18364.8 TTAF | N/A BY BRAND OF F/E INSTALLED - FHTA |
| AD 2009-0278 - ATA 26 - FIRE PROTECTION – PORTABLE HALON 1211 FIRE EXTINGUISHERS – IDENTIFICATION / REPLACEMENT ATA 26 - FIRE PROTECTION – PORTABLE HALON 1211 FIRE EXTINGUISHERS – IDENTIFICATION / REPLACEMENT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | March 15, 2021 | 18364.8 TTAF | N/A BY P/N AMEREX INSTALLED - FHTA |
| AD 2009-24-12 - GAS GENERATOR TURBINE DISC GAS GENERATOR TURBINE DISC | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | November 20, 2014 | 16860.0 TTAF | C/W, NDF - OPSMOB IL |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|---|
| AD 2010-0014 - EQUIPMENT AND FURNISHINGS – HOIST OPERATOR'S BELT SNAP HOOK – REPLACEMENT / MODIFICATION - (25.00.93) EQUIPMENT AND FURNISHINGS – HOIST OPERATOR'S BELT SNAP HOOK – REPLACEMENT / MODIFICATION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | March 15, 2021 | 18364.8 TTAF | N/A BY A/C CONFIGURATION - HOIST NOT INSTALLED - FHTA |
| AD 2010-0062R1 - ATA 26 - FIRE PROTECTION – HALON 1211 FIRE EXTINGUISHERS – IDENTIFICATION / REPLACEMENT - (ASB 26-116) ATA 26 - FIRE PROTECTION – HALON 1211 FIRE EXTINGUISHERS – IDENTIFICATION / REPLACEMENT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | March 15, 2021 | 18364.8 TTAF | N/A by Type & DOM (2021) - FHTA |
| AD 2011-0033 - ATA 29 - HYDRAULIC POWER – FORWARD HYDRAULIC SERVO CONTROL HOSES / PROTECTION INSTALLATION. - (ASB 29.00.13) ATA 29 - HYDRAULIC POWER – FORWARD HYDRAULIC SERVO CONTROL HOSES / PROTECTION INSTALLATION. | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | March 16, 2011 | 14470.09 TTAF | C/W on WO 2562 - ACA13 AMO 75-99 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|---|
| AD 2011-0072 - CANCELLATION NOTICE - ATA 25 - EQUIPMENT & FURNISHINGS – EMERGENCY FLOTATION GEAR ATTACHMENT BRACKETS – INSPECTION / REPLACEMENT. - (ASB 05.00.63) CANCELLATION NOTICE - ATA 25 - EQUIPMENT & FURNISHINGS – EMERGENCY FLOTATION GEAR ATTACHMENT BRACKETS – INSPECTION / REPLACEMENT. | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | January 20, 2022 | 18678.0 TTAF | CANCEL LATION NOTICE - N/A BY CONFIG URATION - FLOATA TION GEAR NOT INSTALL ED - FHTA |
| AD 2011-0103 - EQUIPMENT / FURNISHINGS – EMERGENCY LOCATOR TRANSMITTER (ELT) ANTENNA – MODIFICATION / REPLACEMENT - (SB 02/2011 Issue 1) EQUIPMENT / FURNISHINGS – EMERGENCY LOCATOR TRANSMITTER (ELT) ANTENNA – MODIFICATION / REPLACEMENT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 30, 2011 | 14528.1 TTAF | C/W, NDF - AMO 75-99 ACA 13 |
| AD 2011-0104 - TAIL ROTOR DRIVE – TAIL GEARBOX (TGB) CASING ASSEMBLY –INSPECTION / REPLACEMENT -- (FAA 2013-16-03 / 65.00.46) TAIL ROTOR DRIVE – TAIL GEARBOX (TGB) CASING ASSEMBLY –INSPECTION / REPLACEMENT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | November 05, 2018 | 17203.9 TTAF | N/A BY S/N DA262 INSTALL ED: REPLAC ED 2018 - AMO 203-92 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|---|
| AD 2011-0164R3 - ATA 67 – ROTORS FLIGHT CONTROL – TAIL ROTOR CONTROL STOP SCREWS – INSPECTION - (FAA 2013-17-01 / 05.00.64R1FAA 2013-17-01 / 05.00.64R1) ATA 67 – ROTORS FLIGHT CONTROL – TAIL ROTOR CONTROL STOP SCREWS – INSPECTION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | January 20, 2022 | 18678.0 TTAF | N/A - Auto Pilot Not Installed - FHTA |
| AD 2011-038E - TAIL ROTOR DRIVE – TAIL GEARBOX (TGB) CONTROL LEVER – INSPECTION /REWORK / REPLACEMENT - (05.00.62 Rev 2) TAIL ROTOR DRIVE – TAIL GEARBOX (TGB) CONTROL LEVER – INSPECTION /REWORK / REPLACEMENT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | March 09, 2011 | 14445.8 TTAF | C/W, NDF - ACA 8 AMO 75-99 |
| AD 2011-08-06 - FATIGUE CRACKS IN THE AIRFOIL OF THE POWER TURBINE BLADE - (LTS101-71-00-0253) FATIGUE CRACKS IN THE AIRFOIL OF THE POWER TURBINE BLADE | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | November 20, 2014 | 16860.0 TTAF | N/A - OPSMOBIL |
| AD 2011-23-13 - POWER TURBINE GOVERNOR - (LTS101-73-20-A0268) POWER TURBINE GOVERNOR | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | March 20, 2018 | 12968.8 TTAF | N/A by P/N -11; Converted to -11 IAW SB LTS101-73-20-0280, NDF - Judith Voth 259950 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|--|
| AD 2012-0205 - DOORS – SLIDING DOOR LOWER BALL-JOINT – MODIFICATION - (52.00.34) DOORS – SLIDING DOOR LOWER BALL-JOINT – MODIFICATION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | November 20, 2014 | 16860.0 TTAF | P/C/W ON AUG 19, 2013 - AMO 75-99 ACA 23 |
| AD 2012-0257-E - TAIL ROTOR – LAMINATED HALF-BEARINGS – INSPECTION / REPLACEMENT - (AS350-05.00.71) - Initial - See FHTA Daily AD Sheet TAIL ROTOR – LAMINATED HALF-BEARINGS – INSPECTION / REPLACEMENT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | December 17, 2012 | 15750.7 TTAF | Initial inspection C/wm found satisfactory, NDF. - AMO 75-99 ACA 8 |
| AD 2013-0095-E - ROTOR FLIGHT CONTROLS – MAIN/TAIL ROTOR SERVO-CONTROL BEARINGS – INSPECTION / REPLACEMENT - (FAA 2013-10-51 / 67.00.60) ROTOR FLIGHT CONTROLS – MAIN/TAIL ROTOR SERVO-CONTROL BEARINGS – INSPECTION / REPLACEMENT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | November 20, 2014 | 16860.0 TTAF | P/C/W April 22, 2013. Found to be N/A by P/N - AMO 75- 99 ACA 22 |
| AD 2013-0281R1 - ATA 33 - LIGHTS – POSITION STROBE LIGHT – INSPECTION / DEACTIVATION / MODIFICATION - (FAA 2011-22-05R1 / 05.00.60) ATA 33 - LIGHTS – POSITION STROBE LIGHT – INSPECTION / DEACTIVATION / MODIFICATION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | November 20, 2014 | 16860.0 TTAF | P/C/W Jan 16, 2014 - Found to be N/A Not installed - M475641 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|--|
| ad 2014-0076R3 (Superseded) - ATA 53 - FUSELAGE – REAR STRUCTURE JUNCTION FRAME REINFORCEMENT ANGLES – INSPECTION - (FAA 2016-05-06 / 05.00.62 / 05.00.70) ATA 53 - FUSELAGE – REAR STRUCTURE JUNCTION FRAME REINFORCEMENT ANGLES – INSPECTION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | April 06, 2023 | 18363.9 TTAF | Superseded - Gemini Heli AMO 65-18 GHL-02 |
| AD 2014-0132R1 - MAIN ROTOR – ROTATING STAR SWASHPLATE – INSPECTION / REPLACEMENT - (62.00.34) MAIN ROTOR – ROTATING STAR SWASHPLATE – INSPECTION / REPLACEMENT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | June 27, 2014 | 16387.3 TTAF | C/W IAW ASB 62.00.34, NDF - OPSMOB IL M443959 |
| AD 2014-0233 - ROTOR DRIVE – HYDRAULIC PUMP BEARING – INSPECTION / REPLACEMENT - (ROTOR DRIVE – HYDRAULIC PUMP BEARING – INSPECTION / REPLACEMENT) ROTOR DRIVE – HYDRAULIC PUMP BEARING – INSPECTION / REPLACEMENT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | October 19, 2016 | 16860.0 TTAF | N/A by Bearing P/N 704A33-651-206 installed - FHTA |
| AD 2015-0195 - TAIL ROTOR DRIVE – DRIVE SHAFT BEARINGS – INSPECTION / REPLACEMENT - (01.00.70R1) TAIL ROTOR DRIVE – DRIVE SHAFT BEARINGS – INSPECTION / REPLACEMENT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | July 21, 2018 | 17347.3 TTAF | Tail Rotor Driveshaft bearings inspection completed - Gemini Heli AMO 65-18 GHL1 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|------------------------|-----------------------|------------------------|-----------------------|--------------------|-----------------------|--|
| AD 2016-0021 - ROTOR DRIVE MAIN GEARBOX BOTTOM CASING -INSPECTION/REPLACEMENT 2016-0021 (AS350B2 AND FX) (350A32-0300-05, MGB Bevel Reduction, SN: M1040) | Green | TORQUE CYCLES: 98983.0 | 15489.0 TORQUE CYCLES | 114472.0 TORQUE CYCLES | 27000.0 TORQUE CYCLES | | 87472.0 TORQUE CYCLES | |
| AD 2017-0020R1 - ATA 05 – TAIL ROTOR – PITCH ROD – INSPECTION - (05.00.86) - Initial - See AD Book ATA 05 – TAIL ROTOR – PITCH ROD – INSPECTION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | April 06, 2023 | 18363.9 TTAF | C/W, NDF - Chris Hann GHL-01; AMO 65- 18 |
| AD 2017-0059 - ATA 76 – ENGINE CONTROLS – SWITCHES 53KA, 53KB AND 65K – INSPECTION / MODIFICATION - (05.00.61 / 05.00.77 / 80.00.09) ATA 76 – ENGINE CONTROLS – SWITCHES 53KA, 53KB AND 65K – INSPECTION / MODIFICATION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | January 20, 2022 | 18678.0 TTAF | N/A Honeywel I LTS Engine Installed - FHTA |
| AD 2017-0089R1 - ATA 62– MAIN ROTOR – MAIN ROTOR MAST UPPER BEARING – LUBRICATION / MAIN ROTOR MAST JET OIL HOSE – INSPECTION - (62.00.39) ATA 62– MAIN ROTOR – MAIN ROTOR MAST UPPER BEARING – LUBRICATION / MAIN ROTOR MAST JET OIL HOSE – INSPECTION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | August 21, 2020 | 18323.9 TTAF | P/C/W under AD EU 2017- 0089 R0. No further action required at this time. - Chris Hann GHL-01; AMO 65- 18 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|--|
| AD 2017-0109 - ATA 24 – ELECTRICAL POWER – STARTER GENERATOR AND BRUSHES – INSPECTION / REPLACEMENT - (05.00.88) ATA 24 – ELECTRICAL POWER – STARTER GENERATOR AND BRUSHES – INSPECTION / REPLACEMENT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | April 06, 2023 | 18668.5 TTAF | N/A by P/N 150SG12 2Q4 installed |
| AD 2017-0143 - ATA 24 – ELECTRICAL POWER – DIRECT CURRENT (OPTIONAL) SECOND BATTERY – REPLACEMENT - (24.00.31) ATA 24 – ELECTRICAL POWER – DIRECT CURRENT (OPTIONAL) SECOND BATTERY – REPLACEMENT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | September 07, 2017 | 17185.7 TTAF | N/A Second Battery Not Installed - OPSMOB IL M450092 |
| AD 2018-0152 - ATA 53 – FUSELAGE – MAIN GEARBOX BRACKET BOLTS – INSPECTION - (05.00.92) ATA 53 – FUSELAGE – MAIN GEARBOX BRACKET BOLTS – INSPECTION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | October 19, 2018 | 17491.3 TTAF | C/W, NDF - Gemini Helicopters AMO 65-18 ACA GHL-01 |
| AD 2018-0206 - ATA 62 – MAIN ROTOR – MAST UPPER BEARING SEALANT BEAD / INNER RACE RETAINING RINGS – INSPECTION - (62.00.42) ATA 62 – MAIN ROTOR – MAST UPPER BEARING SEALANT BEAD / INNER RACE RETAINING RINGS – INSPECTION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | October 19, 2018 | 17491.3 TTAF | N/A by P/N 350A37-1076-XX installed - Gemini Heli - AMO 65-18 ACA GHL-01 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|---|
| AD 2018-25-17 - ATA 21 - AIR CONDITIONING - EVAPORATOR BLOWER MOTOR CONNECTOR - REPLACE - (1110014 Rev B) ATA 21 - AIR CONDITIONING - EVAPORATOR BLOWER MOTOR CONNECTOR - REPLACE | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | January 04, 2019 | 17536.7 TTAF | N/A BY CONFIGURATION - NOT INSTALLED - AMO 65-18; GH-01 |
| AD 2019-0060 - ROTORS FLIGHT CONTROL – TAIL ROTOR GEARBOX ACTUATING ROD – INSPECTION - (FAA 2021-16-11 / 67.00.76) ROTORS FLIGHT CONTROL – TAIL ROTOR GEARBOX ACTUATING ROD – INSPECTION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | February 03, 2020 | 18002.3 TTAF | C/W IAW ASB 67-00-76R1 Section 3, NDF AMO 65-18; GH-01 |
| AD 2019-0228 - ATA 25 – EQUIPMENT / FURNISHINGS – ELECTRIC HOIST INSTALLATION – MODIFICATION - (25.00.79) ATA 25 – EQUIPMENT / FURNISHINGS – ELECTRIC HOIST INSTALLATION – MODIFICATION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | January 20, 2022 | 18678.0 TTAF | N/A BY CONFIGURATION - HOST NOT INSTALLED - FHTA |
| AD 2019-16-16 - ENGINE AIR INTAKE SYSTEM - ROTORCRAFT FLIGHT MANUAL SUPPLEMENT - REVISION ENGINE AIR INTAKE SYSTEM - ROTORCRAFT FLIGHT MANUAL SUPPLEMENT - REVISION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | January 20, 2022 | 18678.0 TTAF | N/A by A/C Type -AS350B A - FHTA |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|--|
| AD2020-0064 - Equipment / Furnishings - Emergency Floatation Systems / Inflation Hoses - Inspection - (FAA AD 2020-03-19) Equipment / Furnishings - Emergency Floatation Systems / Inflation Hoses - Inspection | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | January 20, 2022 | 18678.0 TTAF | N/A BY CONFIGURATION - FLOAT KIT NOT INSTALLED - FHTA |
| AD 2020-02-23 - EQUIPMENT / FURNISHINGS - EMERGENCY FLOAT KIT ACTIVATION HANDLE - INSPECTION - (DART SB 2018-07) EQUIPMENT / FURNISHINGS - EMERGENCY FLOAT KIT ACTIVATION HANDLE - INSPECTION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | January 20, 2022 | 18678.0 TTAF | N/A BY CONFIGURATION - FLOAT KIT NOT INSTALLED - FHTA |
| AD 2020-0224R1 - TAIL ROTOR – TAIL ROTOR BLADES – INSPECTION / REPLACEMENT / MODIFICATION - (05.00.99) TAIL ROTOR – TAIL ROTOR BLADES – INSPECTION / REPLACEMENT / MODIFICATION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | October 16, 2020 | 18363.9 TTAF | N/A by Post MOD 075580 TR Blade P/N 355A12-0050-14 installed. - AMO 65-18; GH1-01 Chirs Hann |
| AD 2021-0023 - EQUIPMENT / FURNISHINGS – CYCLIC STICK GRIP UP/DOWN HOIST CONTROL SWITCH – MODIFICATION - (01.00.72) EQUIPMENT / FURNISHINGS – CYCLIC STICK GRIP UP/DOWN HOIST CONTROL SWITCH – MODIFICATION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | January 20, 2022 | 18678.0 TTAF | N/A BY CONFIGURATION - HOIST NOT INSTALLED - FHTA |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|---|
| AD 2021-0048 - ATA 62 – MAIN ROTOR – PITCH ROD UPPER LINKS – MARKING / INSPECTION - (05.01.01) ATA 62 – MAIN ROTOR – PITCH ROD UPPER LINKS – MARKING / INSPECTION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | July 06, 2021 | | C/W IAW ASB 05.01.01 - Gemini Heli - AMO 65-18 ACA GHL-02; Chris Klassen |
| AD 2021-0048 - ATA 62 – MAIN ROTOR – PITCH ROD UPPER LINKS – MARKING / INSPECTION - (05.01.01) - See FHTA Daily AD Sheet ATA 62 – MAIN ROTOR – PITCH ROD UPPER LINKS – MARKING / INSPECTION - See FHTA Daily AD Sheet | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | April 10, 2023 | | |
| AD 2021-0123-E - ATA 29 – HYDRAULIC POWER – TAIL ROTOR LOAD COMPENSATOR – FUNCTIONAL CHECK / MODIFICATION - (29.00.07) HYDRAULIC POWER – TAIL ROTOR LOAD COMPENSATOR – FUNCTIONAL CHECK / MODIFICATION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | January 20, 2022 | 18678.0 TTAF | N/A by A/C S/N - FHTA |
| AD 2021-0168 - ATA 31 – INDICATING / RECORDING SYSTEMS - CONTROL UNIT - INSPECTION - (05.01.00) ATA 31 – INDICATING / RECORDING SYSTEMS - CONTROL UNIT - INSPECTION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | January 20, 2022 | 18678.0 TTAF | N/A by A/C Type -AS350B A - FHTA |
| AD 2021-0194R1 - ATA 05 – TIME LIMITS / MAINTENANCE CHECKS – AIRWORTHINESS LIMITATIONS SECTION –AMENDMENT - (ALS) ATA 05 – TIME LIMITS / MAINTENANCE CHECKS – AIRWORTHINESS LIMITATIONS SECTION –AMENDMENT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | September 10, 2021 | 18670.3 TTAF | Tracking system to reflect changes in the applicable ALS - AMO 65-18; GHL-01 Chris Hann |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|---|
| AD 2021-0282 - TAIL ROTOR – TAIL ROTOR HEAD PITCH CHANGE UNIT BEARING SPACER – MARKING / CHECK - (05.01.03) - Initial - TAIL ROTOR – TAIL ROTOR HEAD PITCH CHANGE UNIT BEARING SPACER – MARKING / CHECK - | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | January 19, 2022 | 18577.3 TTAF | C/W and Marked as per ASB 05.01.03, NDF - Soul Helicopters Philip Hannah ACA 63-10-01 |
| AD 2021-0282 - TAIL ROTOR – TAIL ROTOR HEAD PITCH CHANGE UNIT BEARING SPACER – MARKING / CHECK - (05.01.03) - See FHTA Daily AD Sheet TAIL ROTOR – TAIL ROTOR HEAD PITCH CHANGE UNIT BEARING SPACER – MARKING / CHECK - See FHTA Daily AD Sheet | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | April 10, 2023 | | |
| AD 2022-0051 - ATA 53 - FUSELAGE – REAR STRUCTURE JUNCTION FRAME REINFORCEMENT ANGLES – INSPECTION - (05.00.70 R2) - INITIAL ATA 53 - FUSELAGE – REAR STRUCTURE JUNCTION FRAME REINFORCEMENT ANGLES – INSPECTION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | March 30, 2022 | 18767.6 TTAF | C/W, NDF. Next due 165 H / 12M. - AMO 62-03 HAL ACA 1 |
| AD 2022-0051 - ATA 53 - FUSELAGE – REAR STRUCTURE JUNCTION FRAME REINFORCEMENT ANGLES – INSPECTION - (05.00.70 R2) - See FHTA Daily AD Sheet ATA 53 - FUSELAGE – REAR STRUCTURE JUNCTION FRAME REINFORCEMENT ANGLES – INSPECTION - See FHTA Daily AD Sheet | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | April 10, 2023 | | |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|--------|---------------|----------------------|----------------------|------------------------------------|--------------------|--------------------|--|
| AD 2022-0051 - FUSELAGE - REAR STRUCTUREJUNCTION FRAME REINFORCEMENTANGLERES - INSPECTION ASB AS350-05.00.70R2 (SupercedesEU2014-0076R2) | Green | TTAF: 19644.4 | 117.2 TTAF | 19761.6 TTAF | 165.0 TTAF | August 26, 2023 | 19596.6 TTAF | |
| AD 2022-0077-E - ATA 67 - Rotors Flight Control - Flight Control Flexball Cables - Replacement - (60.00.81) ATA 67 - Rotors Flight Control - Flight Control Flexball Cables - Replacement | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 01, 2022 | 18815.1 TTAF | C.W , NDF and no further action required. - Helicraft Aviation AMO 62- 03-1 |
| AD 2022-0128 - MGB suspension bar mount bolts - (AS350-53.00.65) MGB suspension bar mount bolts | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | June 12, 2022 | | Found to be previousl y complied with 10/19/20 18 TTAF: 17491.3 Gemini Helicopte rs - Brydon MacDoug al |
| AD 2022-0246 - Tap testing of the MR blades ASB AS350-05.01.07 | Green | TTAF: 19644.4 | Permanently Complied | Permanently Complied | 1 month or 55.0 TTAF N/A PCW | December 21, 2022 | 19075.7 TTAF | ASB AS350- 05.01.07 R0 Main Rotor Blades inspectio n not applicabl e to blades installed by PN. Charlie L'Homme cort AOG Friday WO HCT- 22-03 TTAF: 19075.9h rs 21 Decembe r 2022 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|---|
| AD 2022-0246 - Tap testing of the MR blades - (AS350-05.01.07) - Initial Tap testing of the MR blades | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | December 21, 2022 | 0.0 TTAF | NA due to PN MRB's installed. - Charlie L'Homme court AMO 64-21 ACA #2 |
| AD 2022-077-E (2 May 2022) - One time Flight control Flexible Ball Cable Inspection, Ref E ASB AS350-67.00.81 | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 02, 2022 | | Carried out Requirements of AWD 2022-077-E. Found Not applicable by serial number. 2 may 2022 @ 18814.2 FH. Helicraft WO 3215 AMO 62-03 ACA#1 |
| AD 78-193-001(B)R1 - TAIL ROTOR - (05-01) TAIL ROTOR | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | P/C/W DOM 1980 - YZM 219791 |
| AD 78-204-002(B) - MAIN ROTOR SHAFT ASSEMBLY - (65-01) MAIN ROTOR SHAFT ASSEMBLY | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | P/C/W DOM 1980 - YZM 219791 |
| AD 78-227-003(B)R1 - ENGINE/MGB HOUSING - RETIREMENT OF RETIREMENT LIFE - (5-99 R7 MSR) ENGINE/MGB HOUSING - RETIREMENT OF RETIREMENT LIFE | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | P/C/W DOM 1980 - YZM 219791 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|--|
| AD 79-012-004(B) - REAR TRANSMISSION BOX ANCHOR SCREWS - (65-07) REAR TRANSMISSION BOX ANCHOR SCREWS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | P/C/W DOM 1980 - YZM 219791 |
| AD 79-013-005(B) - ROTOR CONTROL YAW CHAIN -(67-01) ROTOR CONTROL YAW CHAIN | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | P/C/W DOM 1980 - YZM 219791 |
| AD 79-104-006(B) - MAIN ROTOR HEAD - (05.03) MAIN ROTOR HEAD | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | P/C/W DOM 1980 - YZM 219791 |
| AD 79-133-007(B) - LEFT HAND LATERAL BAGGAGE HOLD DOOR - (52-04) LEFT HAND LATERAL BAGGAGE HOLD DOOR | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | P/C/W DOM 1980 - YZM 219791 |
| AD 79-134-008(B) - SPHERICAL THRUST BEARINGS - (01-03) SPHERICAL THRUST BEARINGS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | P/C/W DOM 1980 - YZM 219791 |
| AD 79-174-009(B) - TAIL GEARBOX ROTOR SHAFT TIMKEN BEARINGS - (65-08R1) TAIL GEARBOX ROTOR SHAFT TIMKEN BEARINGS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | P/C/W DOM 1980 - YZM 219791 |
| AD 79-217-011(B) - TAIL ROTOR - (65-13) TAIL ROTOR | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | P/C/W DOM 1980 - YZM 219791 |
| AD 80-104-013(B) - MAIN GEARBOX OIL TEMPERATURE PROBE - (65-18) MAIN GEARBOX OIL TEMPERATURE PROBE | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | C/W by Aerospati ale - YZM 219791 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|------------------------------------|
| AD 80-184-015(B)R1 - BOLTS - HUB TO MAIN ROTOR SHAFT - (05-04R1) BOLTS - HUB TO MAIN ROTOR SHAFT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | N/A by P/N installed - YZM 219791 |
| AD 81-067-016(B) - CARGO SWING MECHANICAL RELEASE CONTROL - (25.19) CARGO SWING MECHANICAL RELEASE CONTROL | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | N/A to A/C - YZM 219791 |
| AD 81-084-017(B) - ENGINE - MAIN GEARBOX JUNCTION - (01-06) ENGINE - MAIN GEARBOX JUNCTION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | P/C/W - YZM 219791 |
| AD 81-094-018(B)R2 - MAIN GEAR BOX - (05-06R2) MAIN GEAR BOX | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | N/A by P/N installed - YZM 219791 |
| AD 81-184-020(B) - TAIL ROTOR PITCH CHANGE HORN - (01-07R2) TAIL ROTOR PITCH CHANGE HORN | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | N/A by P/N installed - YZM 219791 |
| AD 81-203-021(B) - UPPER / LOWER FINS - (05-07, 55-02) UPPER / LOWER FINS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | P/C/W N/A by AMS 1046 - YZM 219791 |
| AD 81-223-022(B) - LOWER FIN - (55-02) LOWER FIN | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | P/C/W - YZM 219791 |
| AD 82-023-023(B) - FUEL FILTER - (01-08) FUEL FILTER | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | | N/A - YZM 219791 |
| AD 82-024-024(B) - TAIL ROTOR BLADES LEADING EDGES TAIL ROTOR BLADES LEADING EDGES | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | C/W - YZM 219791 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|---|
| AD 82-098-026(B) - UPPER FIN ATTACHMENT FITTING - (05-09) UPPER FIN ATTACHMENT FITTING | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | | N/A by P/N installed - YZM 219791 |
| AD 82-158-027(B) - FUEL FILTER BY-PASS - (28-05) FUEL FILTER BY-PASS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | N/A by AMS0716 71 - YZM 219791 |
| AD 82-175-029(B) - MAIN GEARBOX - (05-12) MAIN GEARBOX | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | | C/W - YZM 219791 |
| AD 83-075-033(B) - TAIL ROTOR LEADING EDGES - (01-10) TAIL ROTOR LEADING EDGES | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | N/A by P/N installed - YZM 219791 |
| AD 83-173-036(B) - MAIN ROTOR MAST SHAFT - (05-31R1) MAIN ROTOR MAST SHAFT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | N/A by P/N installed - YZM 219791 |
| AD 84-064-037(B)R3 - TAIL ROTOR BLADE SPARS - (05-11R5) TAIL ROTOR BLADE SPARS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 31, 2022 | | NA due to PN. 355A12.0 050.XX TR currently installed - FHFA |
| AD 84-064-037(B)R3 -TAIL ROTOR BLADE SPARS (05-11R5) TAIL ROTOR BLADE SPARS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | C/W - YZM 219791 |
| AD 85-068-038(B) - MAIN GEARBOX BEVEL REDUCTION GEAR MODULE - (05-10R1) MAIN GEARBOX BEVEL REDUCTION GEAR MODULE | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | P/C/W - YZM 219791 |
| AD 85-095-040(B) - MAIN ROTOR SHAFT - (05-15) MAIN ROTOR SHAFT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | | N/A by P/N installed - YZM 219791 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|--|
| AD 85-112-041(B) - FUEL FILTER DRAIN PIPE - (28-06R1) FUEL FILTER DRAIN PIPE | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | Found Embodied - YZM 219791 |
| AD 85-135-042(B) - FUEL FILTER / MAIN GEARBOX FILTERING CARTRIDGES - (01-14A) FUEL FILTER / MAIN GEARBOX FILTERING CARTRIDGES | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | C/W - YZM 219791 |
| AD 86-030-043(B) - EMERGENCY FLOTATION GEAR - (32-06A) EMERGENCY FLOTATION GEAR | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | N/A BY CONFIGURATION - FLOATS NOT INSTALLED - YZM 219791 |
| AD 86-057-044(B)R1 - MAIN ROTOR HEAD - ROVING SLEEVE BEAMS MAIN ROTOR HEAD - ROVING SLEEVE BEAMS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | Found Embodied - YZM 219791 |
| AD 86-070-045(B) - FUEL FILTER DRAIN FUEL FILTER DRAIN | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | C/W IAW AD 86-077-046(B) R2 - YZM 219791 |
| AD 86-077-046(B)R2 - FUEL FILTER - (28-07) FUEL FILTER | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | Found Embodied - YZM 219791 |
| AD 86-097-047(B) - FUEL FILTER - (28-08) FUEL FILTER | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | Found Embodied - YZM 219791 |
| AD 86-10-04 - GAS PRODUCER BLADE DAMPER - (LTS101-72-50-0079 Rev 1) GAS PRODUCER BLADE DAMPER | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | November 20, 2014 | 16860.0 TTAF | C/W, NDF - OPSMOBIL |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|---|
| AD 86-125-048(B)R1 - HELICOPTER GROUND PERFORMANCE - (01-17A) HELICOPTER GROUND PERFORMANCE | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | C/W - YZM 219791 |
| AD 87-088-049(B) - SLIDING DOORS - (52-18) SLIDING DOORS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | N/A - YZM 219791 |
| AD 87-115-050(B) - FLIGHT CYCLE CALCULATION FLIGHT CYCLE CALCULATION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | Found Embodied - YZM 219791 |
| AD 87-161-051(B) - SPHERICAL THRUST BEARING BOLTS - (01-20) SPHERICAL THRUST BEARING BOLTS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | N/A to A/C - YZM 219791 |
| AD 88-14-01 - #3 & 4 BEARINGS / POWER TURBINE DISCS - (LTS101-77-30-0104 Rev 1) #3 & 4 BEARINGS / POWER TURBINE DISCS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | December 13, 2008 | 8608.0 ENG TT | N/A - DELTA P ONLY - CRS C7GR86 1 JW McJunkin - Greer Repair & OH |
| AD 88-184-052(B)R1 - DUNLOP SERVOCONTROLS - (01-21R1) DUNLOP SERVOCONTROLS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | P/C/W - YZM 219791 |
| AD 89-081-053(B) - SPHERICAL THRUST BEARINGS - (01-23) SPHERICAL THRUST BEARINGS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | February 14, 1990 | 0.0 TTAF | P/C/W - YZM 219791 |
| AD 89-155-054(B)R4 - SWASHPLATE BEARING - (62-12R2) SWASHPLATE BEARING | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | September 28, 1998 | 7323.3 TTAF | Found to be N/A by N/A to P/N & S/N of bearing installed - 165-93-122 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|---|
| AD - 90-198-056(B)R1 - BATTERY TEMPERATURE PROBE - (01.29) BATTERY TEMPERATURE PROBE | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | December 18, 1997 | 6807.9 TTAF | C/W, NDF - 165-93-089 |
| AD 91-125(AB) - IMPROVED ELECTRICALBONDING SB 25.62-OL - (25-26-OL) IMPROVED ELECTRICALBONDING SB 25.62-OL | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | July 12, 1991 | | N/A BY CONFIGURATION - HOIST NOT INSTALLED - R.M. M304240 |
| AD 91-137-059(B) - TR PITCH CONTROL LEVER EXPANSION PIN-AARDG - (01.33) TR PITCH CONTROL LEVER EXPANSION PIN-AARDG | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 07, 1991 | 0.0 TTAF | Found to be P/CW - M278993 |
| AD 91-159-060(B) - TAIL ROTOR DRIVESHAFT BEARINGS - (01.34) TAIL ROTOR DRIVESHAFT BEARINGS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | March 19, 1992 | | N/A TO A/C TSN - M278993 |
| AD 91-165-058(B) - ELECTRIC HOIST INSTALLATION - (25.42R1) ELECTRIC HOIST INSTALLATION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | August 22, 1991 | | N/A BY CONFIGURATION - HOIST NOT INSTALLED - R.M. M304240 |
| AD 92-144-061(B) - `JOLLIET` ELT ANTENNA - (25.45) `JOLLIET` ELT ANTENNA | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | August 08, 1992 | | N/A - Not equipped with Affected Antenna - M384089 |
| AD 92-145-062(B) - HYDRAULIC SYSTEM - (01.36) HYDRAULIC SYSTEM | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | October 09, 1992 | | M385499 |
| AD 92-179-064(B)R1 - MAIN ROTOR PITCH CHANGE HORN BUSHES - (62.21) MAIN ROTOR PITCH CHANGE HORN BUSHES | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | September 26, 1992 | | C/W, Found Satisfactory - M385499 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|---|
| AD 93-030-065(B) - MAIN ROTOR MAST ASSEMBLY - (01-41) MAIN ROTOR MAST ASSEMBLY | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | March 25, 1993 | | N/A Not equipped with affected Assy - M381939 |
| AD 93-067-066(B) - FLIGHT IN FALLING SNOW FLIGHT IN FALLING SNOW | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | March 19, 1993 | | N/A by A/C Type - M382528 |
| AD 93-090-067(B)R1 - DOOR 'CLEAR VISION' WINDOW - (05-25R1) DOOR 'CLEAR VISION' WINDOW | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | July 13, 1993 | | N/A - Not Equipped with Sliding Windows - M.T. M387162 |
| AD 93-13-11 - GAS GENERATOR TURBINE ROTOR DISKS - (LTS101-71-00-002) GAS GENERATOR TURBINE ROTOR DISKS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | December 12, 2008 | 8608.0 ENG TT | C/W, NDF - CRS C7GR86 1 JW McJunkin - Greer Repair & OH |
| AD 94-087-068(B) - MGB OIL PRESSURE SWITCH - (ST 01-43) MGB OIL PRESSURE SWITCH | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | July 30, 1994 | | N/A by P/N - M205019 |
| AD 94-180-069(B) - CYCLIC PITCH CHANGE CONTROL ROD - (01-42) CYCLIC PITCH CHANGE CONTROL ROD | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | August 30, 1994 | | C/W, Found Satisfactory - M334522 |
| AD 94-18-06 - #2 BEARING REPLACEMENT - (LTS101-72-50-0163 Rev 1) #2 BEARING REPLACEMENT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | November 20, 2014 | 16860.0 TTAf | C/W, NDF - OPSMOB IL |
| AD 94-279-070(B)R1 - TIMKEN MAIN ROTOR SHAFTS 355A37-0000 ALL DASH #'S - (Telex 01-44) TIMKEN MAIN ROTOR SHAFTS 355A37-0000 ALL DASH #'S | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | February 04, 1995 | | N/A to this A/C - M384026 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|--|
| AD 95-16-04 - AXIAL COMPRESSOR ROTORS - (LTS101-72-30-0088) AXIAL COMPRESSOR ROTORS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | November 20, 2014 | 16860.0 TTAF | C/W, NDF - OPSMOB IL |
| AD 96-12-05 - POWER TURBINE ROTORS - (LTS101-72-50-0144) POWER TURBINE ROTORS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | November 20, 2014 | 16860.0 TTAF | C/W, NDF - OPSMOB IL |
| AD 96-12-27 - GAS GENERATOR TURBINE DISKS - (LTS101-72-50-0150) GAS GENERATOR TURBINE DISKS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | November 20, 2014 | 16860.0 TTAF | N/A - OPSMOB IL |
| AD 96-156-071(B)R1 - MGB SUSPENSION BI-DIRECTIONAL CROSS BEAM - (05.00.28) MGB SUSPENSION BI-DIRECTIONAL CROSS BEAM | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | February 06, 1998 | | C/W - 165-93- 114 |
| AD 98-511-074(A) - SINGLE-POLE CIRCUIT BREAKER - (01.00.47) SINGLE-POLE CIRCUIT BREAKER | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | April 02, 1999 | 7489.2 TTAF | N/A to this A/C - Not equipped - 165-93- 122 |
| AD CF-2000-06R1 - TC SH96 32 - EUROCOPTER CANADA LEFT-SIDE PILOT CONFIGURATION KITS - (ECL-00-67-002) TC SH96 32 - EUROCOPTER CANADA LEFT-SIDE PILOT CONFIGURATION KITS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | September 10, 2002 | 9705.1 TTAF | N/A BY CONFIG URATION - L/H PILOT CONFIG KIT NOT INSTALL ED - GEMINI HELI / M368661 |
| AD CF-2004-10R1 - EUROCOPTER (AEROSPATIALE) AS 350 - HYDRAULIC POWER - (63.00.08 + 29-00-04) - Initial EUROCOPTER (AEROSPATIALE) AS 350 - HYDRAULIC POWER | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | December 02, 2016 | 16959.1 TTAF | C/W,NDF - OPSMOB IL M387533 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|---|
| AD CF-2004-15 - EUROCOPTER AS 350 HELICOPTERS – HYDRAULIC CUT-OFF FUNCTION - (SB 29.00.07) EUROCOPTER AS 350 HELICOPTERS – HYDRAULIC CUT-OFF FUNCTION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | September 22, 2014 | 10885.3 TTAF | P/C/W IAW AD 2004-089 & SB 29-00-07 - GEMINI HELI / M368661 |
| AD CF-2005-16 - BATTERY FUSE CIRCUIT - (SB-ECL-113 R1) BATTERY FUSE CIRCUIT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | June 22, 1995 | 11165.9 TTAF | N/A BY CONFIGURATION - BATTERY RELOCATION KIT NOT INSTALLED - GEMINI HELI / M368661 |
| AD CF-2007-19R1 - HYDRAULIC TEST SWITCH PROTECTION - (67.00.32) HYDRAULIC TEST SWITCH PROTECTION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | December 15, 2008 | 13268.7 TTAF | N/A BY CONFIGURATION - HONEYWELL PANEL NOT INSTALLED - Greg Monk ACA 13 AMO 75-99 |
| AD CF-2015-10 - STCSR00825NYD - HYDRAULIC POWER - INADVERTENT ACTUATION OF HYDRAULIC TEST SWITCH - (STC SR00825NY-D) STCSR00825NYD - HYDRAULIC POWER - INADVERTENT ACTUATION OF HYDRAULIC TEST SWITCH | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | January 20, 2022 | 18678.0 TTAF | N/A - STC Not Installed - FHTA |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|---|
| AD CF-2017-37 - ATA 67 - FLIGHT CONTROLS – RESTRICTION OF DIRECTIONAL CONTROL PEDAL MOVEMENT - (SB-AHCA-128) ATA 67 - FLIGHT CONTROLS – RESTRICTION OF DIRECTIONAL CONTROL PEDAL MOVEMENT | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 26, 2018 | 17203.9 TTAF | C.W as per SB AHCA-128,NDF - OPSMOB IL M450092 |
| AD CF-2019-01 - STANDARD PRACTICES – HELICOPTER EXTERNAL TRANSPORT SYSTEM (HETS™) - UNAPPROVED PARTS, INADEQUATE SERVICE LIFE LIMITS AND MAINTENANCE REQUIREMENTS - (MMS-AS350/55) STANDARD PRACTICES – HELICOPTER EXTERNAL TRANSPORT SYSTEM (HETS™) - UNAPPROVED PARTS, INADEQUATE SERVICE LIFE LIMITS AND MAINTENANCE REQUIREMENTS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | April 30, 2019 | 17627.0 TTAF | N/A by Configuration - HETS Not Installed - AMO 65018; GCL-01 |
| AD CF-2021-53 - ATA 34 – NAVIGATION – ROTORCRAFT – PROHIBITION OF OPERATIONS REQUIRING RADIO ALTIMETER IN THE PRESENCE OF 5G C-BAND WIRELESS BROADBAND INTERFERENCE - (FAA AD 2021-23-13) ATA 34 – NAVIGATION – ROTORCRAFT – PROHIBITION OF OPERATIONS REQUIRING RADIO ALTIMETER IN THE PRESENCE OF 5G C-BAND WIRELESS BROADBAND INTERFERENCE | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | March 30, 2022 | 18767.6 TTAF | C/W AWD inserted into AFM and flight crew informed. - AMO 62-03 HAL ACA 1 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|--------|---------------|----------------------|----------------------|----------------------|--------------------|--------------------|---|
| AD CF-82-02 - IMPELLER AND FUEL PUMP COVER - (391-28-81SL) IMPELLER AND FUEL PUMP COVER | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | N/A MOD C - YZM 219791 |
| AD CF-84-11 - FREEZING - MAIN SERVO CONTROL VALVE - (67.05) FREEZING - MAIN SERVO CONTROL VALVE | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 1989 | 0.0 TTAF | Found Embodied - YZM 219791 |
| AD CF-98-15 - STCSH823 - EXTERNAL RESCUE SYSTEMS - (CAR 702.21) STCSH823 - EXTERNAL RESCUE SYSTEMS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | January 20, 2022 | 18678.0 TTAF | N/A - STC Not Installed - FHATA |
| AD EU2015-0195 - TAIL ROTOR DRIVE - DRIVE SHAFTBEARINGS - INSPECTION/REPLACEMENT EU2015-0195 | Green | TTAF: 19644.4 | 117.2 TTAF | 19761.6 TTAF | 165.0 TTAF | August 26, 2023 | 19596.6 TTAF | |
| Ad F-2000-222-079R1 - TAIL ROTOR PITCH CHANGE ROTATING PLATES - (05.00.33) TAIL ROTOR PITCH CHANGE ROTATING PLATES | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | October 04, 2004 | 10909.4 TTAF | N/A BY P/N 350A33-2030-00 INSTALLED - GEMINI HELI / M368661 |
| AD F-2000-302 - ATA 28 - FERRY FUEL TANKS - (28.00.14) ATA 28 - FERRY FUEL TANKS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | November 30, 2000 | | N/A BY A/C CONFIGURATION - FERRY FUEL TANKS NOT INSTALLED - GEMINI HELI / M368661 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|---|
| AD F-2001-580-085R2 - TAIL SERVOCONTROLS - EYE END FITTING LOCKING - (05.00.37) TAIL SERVOCONTROLS - EYE END FITTING LOCKING | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | June 19, 2002 | 0.0 TTAF | P/C/W IAW AD 2001-580-085(A)R1 - GEMINI HELI / M368661 |
| AD F-2002-281-091R1 - AS 350 HELICOPTERS - NAVIGATION - HSI KI 525A - (HIS KI 525A) AS 350 HELICOPTERS - NAVIGATION - HSI KI 525A | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | March 25, 2004 | 9437.8 TTAF | N/A HSI P/N K1525A NOT INSTALLED - GEMINI HELI / M368661 |
| AD F-2002-452R1 - VARIOUS ATA - MAIN + TAIL ROTOR DYNAMIC COMPONENTS - (62.00.25) VARIOUS ATA - MAIN + TAIL ROTOR DYNAMIC COMPONENTS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 03, 2003 | 9705.1 TTAF | N/A - SUBJECT OF THIS REVISION DOES NOT AFFECT THIS A/C - GEMINI HELI / M368661 |
| AD F-2003-002R1 - AS 350B SERIES + AS 350D - CYCLIC STICK BINDING - (67.00.24) AS 350B SERIES + AS 350D - CYCLIC STICK BINDING | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | February 23, 2014 | 9749.6 TTAF | N/A FRICTION CUP MODEL AFFECT BY THIS AD NOT INSTALLED ON A/C - GEMINI HELI / M368661 |
| AD F-2003-260R1 - BATTERY LUG CONNECTION - (24.00.1) BATTERY LUG CONNECTION | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | June 21, 2004 | 9814.6 TTAF | P/C/W ON JULY 11, 2003 - GEMINI HELI / M368661 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|---|--------|---------------|----------------------|----------------------|----------------------|--------------------|--------------------|--|
| AD F-2003-322R1 - ROTOR FLIGHT CONTROLS - DOUBLE LOCKING OF THE STOP SCREWS - (67.00.25 R1) ROTOR FLIGHT CONTROLS - DOUBLE LOCKING OF THE STOP SCREWS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | June 21, 2004 | 10133.9 TTAF | P/C/W ON SPETEMBER 4, 2003 - GEMINI HELI / M368661 |
| AD F-2004-033 - AS 350 MODELS - FUEL BLEED LEVER - (28.00.16) AS 350 MODELS - FUEL BLEED LEVER | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 27, 2004 | 10466.5 TTAF | C/W - GEMINI HELI / CLINT G. M368129 |
| AD F-2004-035 - AS 350 MODELS - REAR STRUCTURE JUNCTION FRAME - (ASB 05.00.43) - Initial AS 350 MODELS - REAR STRUCTURE JUNCTION FRAME | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | January 21, 2005 | 11025.4 TTAF | C/W, NDF - AMO 75-99 M368661 |
| AD F-2004-035 - - REAR STRUCTURE JUNCTION FRAME F-2004-035 | Green | TTAF: 19644.4 | 259.8 TTAF | 19904.2 TTAF | 550.0 TTAF | June 03, 2023 | 19354.2 TTAF | N/A due to tail junction equipped with reinforcement angles |
| AD F-2004-055 - EUROCOPTER AS 350 - REPLACEMENT OF HYDRAULIC FLUID - (ASB 05.00.45) - Initial EUROCOPTER AS 350 - REPLACEMENT OF HYDRAULIC FLUID | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | April 27, 2004 | 10425.9 TTAF | Inspection schedule and tracking system have been modified - AMO 75-99 M368661 |
| AD F-2004-170R1 - EQUIPMENT AND FURN. - HOISTS HOOKS - (01.00.56) EQUIPMENT AND FURN. - HOISTS HOOKS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | April 12, 2005 | 11025.4 TTAF | N/A BY CONFIRMATION HOIST NOT INSTALLED - GEMINI HELI / M368661 |

| Reminder | Status | Current | Time Remaining | Due | Interval | Last Complied Date | Last Complied Time | Method of Compliance |
|--|--------|---------|----------------------|----------------------|----------------------|--------------------|--------------------|--|
| AD F-2004-174 - HYDRAULIC POWER - HYDRAULIC POWER LOSS - (AFM) HYDRAULIC POWER - HYDRAULIC POWER LOSS | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | November 11, 2004 | 10993.7 TTAF | P/C/W IAW CF 2003-15R2 ON OCTOBER 18, 2004 - GEMINI HELI / M368661 |
| AD F-2004-178 - TAIL ROTOR BLADE TRAILING EDGE TAB - (ASB 64.00.05) TAIL ROTOR BLADE TRAILING EDGE TAB | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | February 16, 2005 | 11025.4 TTAF | C/W IAW ASB 64.00.05 - GEMINI HELI / M368661 |
| AD F-2005-042 - ROTOR FLIGHT CONTROLS-YAW CONTROL - (67.00.25R1) ROTOR FLIGHT CONTROLS-YAW CONTROL | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | May 22, 2005 | 11077.0 TTAF | C/W - GEMINI HELI / M368661 |
| AD G-2003-0008 - CAMERA SYSTEM INSTALLATION - REWORK MOUNTINGPANEL, MOD 350-1521 OR 1680 , SB-A25-001 - (350-1521 + 1680) CAMERA SYSTEM INSTALLATION - REWORK MOUNTINGPANEL, MOD 350-1521 OR 1680 , SB-A25-001 | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | September 19, 2003 | | N/A BY A/C CONFIGURATION - CAMERA SYSTEM NOT INSTALLED - GEMINI HELI / M368661 |
| AD G-2004-0019 - CAMERA INSTALLATION-FLOOR MOUNTED HOLD DOWN HOOK - MAG(E) SB-A25-002, ISSUE 1 - (SB-A25-2002) CAMERA INSTALLATION-FLOOR MOUNTED HOLD DOWN HOOK - MAG(E) SB-A25-002, ISSUE 1 | Green | | Permanently Complied | Permanently Complied | PCW NON RECURRING | August 05, 2004 | 10731.6 TTAF | N/A BY A/C CONFIGURATION - CAMERA SYSTEM NOT INSTALLED - GEMINI HELI / M368661 |