

Foothills Helicopter Training academy

Unit 35, 4 Winters Way
Okotoks, AB T1S0J1
Jacki • Jacki@foothillsheli.com
AMO#: 64-23



Reminders

Report date: October 30, 2023

Included in this report:

C-FRIT

C-FRIT

Robinson Helicopters R22 1911

HOBBS: 20.1 • TTAF: 6082.2

O-320-B2C, Lycoming Engine: 1283.4 SINCE OVERHAUL (TTAF), 6068.2 SINCE NEW (TTAF)

Reminder	Status	Current	Time Remaining	Due	Interval	Last Complied Date	Last Complied Time	Method of Compliance
12 Month First Aid Kit Inspection	Red		7 days	07 Nov 2023	10 months 29 days	December 09, 2022		
12 Month Compass Swing	Yellow		about 1 month	09 Dec 2023	12 months	December 09, 2022		
12 Month Fire Extinguisher Inspection	Yellow		about 1 month	09 Dec 2023	12 months	December 09, 2022		
24 Month Pitot static and Transponder Checks	Yellow		3 months	24 Jan 2024	24 months	January 24, 2022		
24 Month Pitot Static check	Yellow		3 months	24 Jan 2024	24 months	January 24, 2022		
400HR Engine Inspection	Green	TTAF: 6082.2	120.7 TTAF	6202.9 TTAF	400.0 TTAF	January 27, 2023	5802.9 TTAF	
2200HR Pinion Replacement P/N A146-1 S/N 11017, MRGB (A006-6, Main Rotor Gearbox Assy, SN: 4718)	Green	TTAF: 6082.2	705.2 TTAF	6787.4 TTAF	2200.0 TTAF	August 15, 2016	4587.4 TTAF	
500 hour CMI SB 658 Distributor Gear Inspection	Green	TTAF: 6082.2	170.2 TTAF or about 3 years	6252.4 TTAF or 06 Jan 2027	48 months or 500.0 TTAF	January 06, 2023	5752.4 TTAF	
500HR/4YR LH Magneto Inspection CMI SB 643 (10-600614-1, Magneto LH, SN: K029207E)	Green	TTAF: 6082.2	170.2 TTAF or about 3 years	6252.4 TTAF or 06 Jan 2027	48 months or 500.0 TTAF	January 06, 2023	5752.4 TTAF	
500HR/4YR LH Magneto Inspection CMI SB 663 (10-600614-1, Magneto LH, SN: K029207E)	Green	TTAF: 6082.2	170.2 TTAF or about 3 years	6252.4 TTAF or 06 Jan 2027	48 months or 500.0 TTAF	January 06, 2023	5752.4 TTAF	
500HR/4YR LH Magneto Inspection CMI SB 670 (10-600614-1, Magneto LH, SN: K029207E)	Green	TTAF: 6082.2	170.2 TTAF or about 3 years	6252.4 TTAF or 06 Jan 2027	48 months or 500.0 TTAF	January 06, 2023	5752.4 TTAF	
500HR/4YR RH Magneto Inspection CMI SB 643 (10-600664-201, Magneto RH, SN: E03FA073R)	Green	TTAF: 6082.2	170.2 TTAF or about 3 years	6252.4 TTAF or 06 Jan 2027	48 months or 500.0 TTAF	January 06, 2023	5752.4 TTAF	

Reminder	Status	Current	Time Remaining	Due	Interval	Last Complied Date	Last Complied Time	Method of Compliance
500HR/4YR RH Magneto Inspection CMI SB 663 (10-600664-201, Magneto RH, SN: E03FA073R)	Green	TTAF: 6082.2	170.2 TTAF or about 3 years	6252.4 TTAF or 06 Jan 2027	48 months or 500.0 TTAF	January 06, 2023	5752.4 TTAF	
500HR/4YR RH Magneto Inspection CMI SB 670 (10-600664-201, Magneto RH, SN: E03FA073R)	Green	TTAF: 6082.2	170.2 TTAF or about 3 years	6252.4 TTAF or 06 Jan 2027	48 months or 500.0 TTAF	January 06, 2023	5752.4 TTAF	
2000HR Engine Overhaul (O-320-B2C, Lycoming Engine, SN: L16891-39A)	Green	TTAF: 6082.2	702.6 TTAF	6784.8 TTAF	2000.0 TTAF	March 28, 2023	4784.8 TTAF	
1964HR Screw Retirement P/N NAS1351-4-20, Pitch Horn	Green	TTAF: 6082.2	727.7 TTAF	6809.9 TTAF	1964.0 TTAF	September 21, 2018	4845.9 TTAF	
100HR AD 2005-16-05 - TechTool high visibility windows inspection	Green	TTAF: 6082.2	39.8 TTAF	6122.0 TTAF	100.0 TTAF	September 19, 2023	6022.0 TTAF	
100 HR Engine Inspection	Green	TTAF: 6082.2	39.8 TTAF or 11 months	6122.0 TTAF or 19 Sep 2024	12 months or 100.0 TTAF	September 19, 2023	6022.0 TTAF	
100 HR Lycoming SI 1080 Inspection	Green	TTAF: 6082.2	39.8 TTAF	6122.0 TTAF	100.0 TTAF	September 19, 2023	6022.0 TTAF	
12 Yr Airframe Inspection	Green		almost 5 years	15 Aug 2028	144 months	August 15, 2016		
2200HR/12YR Bearing Replacement, T/R Pitch Control (A031-1, Tail Rotor Pitch Control, SN: 8248)	Green	TTAF: 6082.2	902.6 TTAF or almost 5 years	6984.8 TTAF or 15 Aug 2028	144 months or 2200.0 TTAF	August 15, 2016	4784.8 TTAF	
24 Month ELT Inspection	Green		10 months	24 Aug 2024	24 months	August 24, 2022		
2200 FH Airframe Inspection.	Green	TTAF: 6082.2	902.6 TTAF	6984.8 TTAF	2200.0 TTAF	October 03, 2023	4784.8 TTAF	
2200HR Gear Set Retirement P/N B545-1 S/N 3633, TRGB (B021-1, Tail Rotor Gearbox, SN: 1496)	Green	TTAF: 6082.2	902.6 TTAF	6984.8 TTAF	2200.0 TTAF	August 15, 2016	4784.8 TTAF	
2200HR Pinion Retirement, TRGB (B021-1, Tail Rotor Gearbox, SN: 1496)	Green	TTAF: 6082.2	902.6 TTAF	6984.8 TTAF	2200.0 TTAF	August 15, 2016	4784.8 TTAF	
AAIR	Green		5 months	31 Mar 2024	12 months	March 31, 2023		

Reminder	Status	Current	Time Remaining	Due	Interval	Last Complied Date	Last Complied Time	Method of Compliance
2200HR/12YR M/R Hub Assy Inspection Ch. 1.102 (B370-1, Main Rotor Hub Assy, SN: 0413)	Green	TTAF: 6082.2	963.7 TTAF or almost 7 years	7045.9 TTAF or 21 Sep 2030	144 months or 2200.0 TTAF	September 21, 2018	4845.9 TTAF	
2200HR M/R Spindle Retirement P/N A158-3 S/N 0795 (A016-6, M/R Blade, SN: 5050)	Green	TTAF: 6082.2	963.7 TTAF	7045.9 TTAF	2200.0 TTAF	September 21, 2018	4845.9 TTAF	
2200HR M/R Spindle Retirement P/N A158-3 S/N 0796 (A016-6, M/R Blade, SN: 5072)	Green	TTAF: 6082.2	963.7 TTAF	7045.9 TTAF	2200.0 TTAF	September 21, 2018	4845.9 TTAF	
800HR Bearing Inspection, Lower Sheave (A181-4 Rev.N)	Green	TTAF: 6082.2	439.5 TTAF or about 3 years	6521.7 TTAF or 15 Dec 2026	48 months or 800.0 TTAF	December 15, 2022	5721.7 TTAF	
SB-120 PART B - Replacement of TR blades	Red		about 1 year	31 Dec 2024	24 months	December 31, 2022		
150HR AD CF-90-03R2 Part 1 - Exhaust type cockpit/cabin heaters (muff) inspect pipes & tubes to detect deterioration (O-320-B2C, Lycoming Engine, SN: L16891-39A)	Green	TTAF: 6082.2	89.8 TTAF or 11 months	6172.0 TTAF or 19 Sep 2024	12 months or 150.0 TTAF	September 19, 2023	6022.0 TTAF	
50HR CMI SB 366 Carburetor Throttle Body Screw Inspection	Green	TTAF: 6082.2	30.2 TTAF	6112.4 TTAF	50.0 TTAF	October 17, 2023	6062.4 TTAF	
ELT Battery Replacement	Green		about 4 years	20 Nov 2027	72 months	November 20, 2021		
300HR DART Cabin Floor protectors Inspection	Green	TTAF: 6082.2	212.3 TTAF	6294.5 TTAF	300.0 TTAF	August 12, 2023	5994.5 TTAF	
300HR Inspection Lycoming SB 301	Green	TTAF: 6082.2	212.3 TTAF	6294.5 TTAF	300.0 TTAF	August 12, 2023	5994.5 TTAF	
300HR Inspection Lycoming SB 388C	Green	TTAF: 6082.2	212.3 TTAF	6294.5 TTAF	300.0 TTAF	August 12, 2023	5994.5 TTAF	Genesis 22-FRIT1151
Air Filter Replacement (B771-1 Air Filter)	Green	TTAF: 6082.2	515.0 TTAF or almost 4 years	6597.2 TTAF or 22 Aug 2027	60 months or 600.0 TTAF	August 22, 2022	5997.2 TTAF	
12 Month Capacity Check (Initial) (RG-25XC Concorde Lead Acid Battery (12V), SN: 41200146)	Green		10 months	31 Aug 2024	12 months	August 11, 2023		
12YR CMI SB 643 RH Magneto (10-600664-201, Magneto RH, SN: E03FA073R)	Green		almost 10 years	23 Sep 2033	144 months	September 23, 2021	5287.9 TTAF	

Reminder	Status	Current	Time Remaining	Due	Interval	Last Complied Date	Last Complied Time	Method of Compliance
500HR Inspection	Green	TTAF: 6082.2	439.8 TTAF or almost 4 years	6522.0 TTAF or 19 Sep 2027	48 months or 500.0 TTAF	September 19, 2023	6022.0 TTAF	
12 Month ELT S/N 11240 Inspection	Green		11 months	02 Oct 2024	12 months	October 02, 2023		
12YR CMI SB 643 LH Magneto (10-600614-1, Magneto LH, SN: K029207E)	Green		about 11 years	06 Jan 2035	144 months	January 06, 2023	5287.9 TTAF	
50 hour / 4 month Lycoming SB 480 Oil & Filter	Green	TTAF: 6082.2	47.6 TTAF or 4 months	6129.8 TTAF or 29 Feb 2024	4 months or 50.0 TTAF	October 29, 2023	6079.8 TTAF	
50 hour Lycoming SI 1080 Inspection	Green	TTAF: 6082.2	47.6 TTAF	6129.8 TTAF	50.0 TTAF	October 29, 2023	6079.8 TTAF	
50HR Engine Inspection	Green	TTAF: 6082.2	47.6 TTAF or 4 months	6129.8 TTAF or 29 Feb 2024	4 months or 50.0 TTAF	October 29, 2023	6079.8 TTAF	
100 HR Airframe Inspection	Green	TTAF: 6082.2	97.6 TTAF or 12 months	6179.8 TTAF or 29 Oct 2024	12 months or 100.0 TTAF	October 29, 2023	6079.8 TTAF	
100 HR CMI SB 643 LH Magneto Inspection (10-600614-1, Magneto LH, SN: K029207E)	Green	TTAF: 6082.2	97.6 TTAF	6179.8 TTAF	100.0 TTAF	October 29, 2023	6079.8 TTAF	
100 HR CMI SB 643 RH Magneto Inspection (10-600664-201, Magneto RH, SN: E03FA073R)	Green	TTAF: 6082.2	97.6 TTAF	6179.8 TTAF	100.0 TTAF	October 29, 2023	6079.8 TTAF	
100 HR Lycoming SI 1129 DC Alternator & Generator Belt Tension	Green	TTAF: 6082.2	97.6 TTAF	6179.8 TTAF	100.0 TTAF	October 29, 2023	6079.8 TTAF	
100 HR Lycoming SI 1191 Cylinder Compression Inspection	Green	TTAF: 6082.2	97.6 TTAF	6179.8 TTAF	100.0 TTAF	October 29, 2023	6079.8 TTAF	
100HR AD 2005-16-05 - TechTool high visibility windows inspection - Initial Compliance	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 15, 2016		C/W, NDF by G. Novak / 474071.
AD 2000-08-09 - Sprag Clutch (SB-85)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	May 25, 2000		C/W,NDF - TCB Astone for M408025
AD 2000-20-51 - Yoke Half Assembly Inspection (SB-88A)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	February 15, 2001		C/W KI-152 Installed - TCB Astone for M408025
AD 2003-04-04 - R22 Series - Tail Rotor Pitch Change Bearing (SB90A) - Initial	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	October 03, 2003		N/A by Revision "L" Installed, NDF. - TCB Astone for 70-03 / 421768

Reminder	Status	Current	Time Remaining	Due	Interval	Last Complied Date	Last Complied Time	Method of Compliance
AD 2003-04-04 - R22 Series - Tail Rotor Pitch Change Bearing (SB90A) - Terminating Action	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	October 03, 2003		Revision "L" Installed. No further action required. - TCB Astone for 70-03 / 421768
AD 2004-06-52 - M/R Blades Failure. Superseded by 2004-19-09	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	September 19, 2004		Superseded by 2004-19-09
AD 2004-10-14 - Inspection after sudden Stoppage (MSB 475C)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	C/W, NDF - SCA 15 / PAAL SCA 11 AMO 15-82
ad 2004-19-09 - M/R Blades Fatigue Cracks (AWL)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	April 04, 2006		N/A by P/N - Matt Willemsen / M753272
AD 2005-26-10 - Has Been Superseded By 2006-12-07	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	April 05, 2023		Has Been Superseded By 2006-12-07
AD 2006-12-07 - Eci Cylinders - (05-08 Rev 2)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	Determined to be N/A by P/N - PAAL SCA 11 AMO 15-82
AD 2007-04-19R1 - SAP Cylinders (SAP B06-01, Rev E)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	Determined to be N/A by P/N of Lycoming cylinders installed - SCA 15 / PAAL SCA 11 AMO 15-82
AD 2007-26-12 - This AD has been superseded by 2011-12-10 (SERVICE LETTER SL-56)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	December 17, 2012		superseded by 2011-12-10
AD 2008-19-05 - Eci Cylinders - SUPERSEDED	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	April 05, 2023		SUPERSEDED
AD 2009-26-12 - Eci Cylinders	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	N/A by P/N - PAAL SCA 11 AMO 15-82
AD 2010-24-03 - T/R Flight Controls (SB-97)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 15, 2016		0.050 Supports installed IAW SB-97. - G. Novak / 474071
AD 2011-12-10 - This AD has been superseded by 1014-23-16 - (SB-103; SL-56B)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	January 03, 2012		superseded by 2014-23-16
AD 2012-03-07 - Carburetor	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	N/A by P/N (10-527) - PAAL SCA 11 AMO 15-82
AD 2013-19-06 - Fuel Shutoff Valve (SB-105 (info only))	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	September 04, 2014		C/W April 12, 2012, No further action required. - G. Novak / 474071

Reminder	Status	Current	Time Remaining	Due	Interval	Last Complied Date	Last Complied Time	Method of Compliance
AD 2014-23-16 - M/R blade debonding (SL-56, and SB 103A) - Initial	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 15, 2016		C/W, paint refinished, NDF. - G. Novak / 474071
AD 2014-23-16 - M/R blade debonding (SL-56, and SB 103A) - Terminating Action	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	September 21, 2018		A016-6 M/R Blades installed 21 Sep 2018 under WO 235-RIT, no further action required. - G. Novak / 474071
AD 2017-16-11 - ATA 82 - Reciprocating Engine Power Section - Connecting Road Failure (SB 632B)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	September 21, 2018		N/A by S/N & DOM - G.Novak / 474071
AD 2021-23-13 - ATA 34 - Navigation - Radio Altimeter - Interference - RFM Revision	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	March 29, 2022	5392.9 TTAF	C/W, NDF. - FHFA/ExHeli
AD 2022-12-08 Engine RPM Indicating System.	Green		Permanently Complied	Permanently Complied	25 days N/A PCW	July 06, 2022		NA by AC SN. No action required. Genesis WO: 22-FRIT1169
AD 55-02-02 - Gasket - Lower Accessory Drive Adapter Cover - (SB 176)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	N/A by Date - PAAL SCA 11 AMO 15-82
AD 59-10-07 - Cylinder Baffle Clamps - (SB 254A)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	N/A by Date - PAAL SCA 11 AMO 15-82
AD 63-23-02 - Exhaust Valve System / Camshaft - (SB 293B)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	N/A by Date - PAAL SCA 11 AMO 15-82
AD 64-16-05 - AC Fuel Pump - (SB 298)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	N/A by Date - PAAL SCA 11 AMO 15-82
AD 66-06-03 - Connecting Rod Assemblies - (SB 302)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	N/A by Date - PAAL SCA 11 AMO 15-82
AD 66-20-04 - Oil Filter Adapter Gasket - (SB 307)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	N/A by Date - PAAL SCA 11 AMO 15-82
AD 67-01-04 - Oil Filters - (SB 1A)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	N/A by P/N - PAAL SCA 11 AMO 15-82
AD 69-24-03 - Carburetors - (A1-69)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	N/A by Date - PAAL SCA 11 AMO 15-82
AD 73-23-01R4 - Piston Pins - (SB 367F)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	N/A by P/N - PAAL SCA 11 AMO 15-82

Reminder	Status	Current	Time Remaining	Due	Interval	Last Complied Date	Last Complied Time	Method of Compliance
AD 75-08-09 - Oil Pump Drive Shaft/Impeller - (SB 381B, 385C)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	Found to be P/C/W, NDF - PAAL SCA 11 AMO 15-82
AD 80-06-05 - Hardness Tests on Impulse Coupling Rivets	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	N/A by P/N - PAAL SCA 11 AMO 15-82
AD 80-11-07 - Main Rotor blade Structural Failure	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	June 10, 1994		N/A by DOM - D408025
AD 80-21-53 - Main Transmission Gears	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	June 10, 1994		N/A by DOM - D408025
AD 80-24-01 - Tailcone	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	June 10, 1994		N/A by DOM - D408025
AD 80-26-06 - Tail rotor Plate	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	June 10, 1994		N/A by DOM - D408025
AD 81-05-52R1 - Main Gearbox	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	June 10, 1994		N/A by DOM - D408025
AD 81-17-01 - Starting Vicrbator Assemblies	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	June 10, 1994		N/A by DOM - D408025
AD 82-03-07 - Main Rotor Blades	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	June 10, 1994		N/A by DOM - D408025
AD 82-11-01 - Steel Tube Frame	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	June 10, 1994		N/A by DOM - D408025
AD 82-15-07 - Tail Rotor Drive Shaft	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	June 10, 1994		N/A by DOM - D408025
AD 83-15-07R1 - Main Rotor Blade Inspection	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	June 10, 1994		N/A by DOM - D408025
Ad 84-18-04 - Main Rotor Gearbox	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	June 10, 1994		N/A by DOM - G. Novak / 474071
AD 87-10-06R1 - Rocker Arm Assembly - (477A)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	N/A by Date - PAAL SCA 11 AMO 15-82
AD 87-18-03 - Main Rotor Pitch Link Assy	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	June 10, 1994		N/A by DOM - D408025

Reminder	Status	Current	Time Remaining	Due	Interval	Last Complied Date	Last Complied Time	Method of Compliance
AD 88-26-01R2 - A158-1 M/R Spindle (60 Technical Report) - Initial	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	July 15, 1996		C/W, NDF - Matt Willemssen / M753272
AD 88-26-01R2 - A158-1 M/R Spindle (60 Technical Report) - Terminating Action	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	September 21, 2018		A158-3 Spindles installed 21 Sep 2018 Under WO 235-RIT - G. Novak / 474071
AD 90-04-06R1 - Propeller Governor Oil Line and Fitting - (488A and SIL 1435 1)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	N/A by Engine P/N - PAAL SCA 11 AMO 15-82
AD 90-17-01 - Carb Airbox Latch Removal - (SB-61)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	June 10, 1994		C/W when a/c was imported. Carb latches not installed. - confirmed by Access Heli AMO 69-14
AD 91-08-07 - Fuel Pump vent hose fitting leak check - (494, 497 + SI 1460)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	N/A by Date - PAAL SCA 11 AMO 15-82
AD 91-14-22 - Has Been Superseded by2004-10-14	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	April 05, 2023		Has Been Superseded by2004-10-14
AD 92-06-17 - Bolt Failures p/n NAS1304-16 - (SB-69)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	October 26, 2009		Previously c/w as per SB-69 10 June 2009 - Matt Willemssen / M753272
AD 92-12-05 - Piston Pins - (501 rev B)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	N/A by P/N - PAAL SCA 11 AMO 15-82
AD 93-11-11 - Fuel Pumps - (Aero Accessories 002)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	N/A by Engine P/N - PAAL SCA 11 AMO 15-82
AD 93-19-04 - Carburetors - (CF-1-92Rev1)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	N/A by Date - PAAL SCA 11 AMO 15-82
AD 94-15-08 - M/R Blade Inspection - (SB-72)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	October 03, 2003		N/A by S/N - TCB Astone for M408025
AD 95-06-03 - M/R Mast Separation-Spanner Nuts - (SB-76)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	October 26, 2009		N/A Gearbox manufactured on Dec 9 2009 - Matt Willemssen / M753272
AD 95-07-01 - Connection Rod Bolts - (Superior Air #95-002)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	N/A by P/N - PAAL SCA 11 AMO 15-82
AD 95-11-09 - Placard Low G Cyclic Pushover (SB-79)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	June 14, 1995		Placard (push over prohibit) -

Reminder	Status	Current	Time Remaining	Due	Interval	Last Complied Date	Last Complied Time	Method of Compliance
AD 95-23-05 - T/R Output Key - (Supersedes 94-17-07)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	October 26, 2009		94-17-07 c/w on 16 may 95 - Matt Willemssen / M753272
AD 95-26-02 - Lycoming Engine Specific Inspections - (398, SI 1191)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	Determined to be N/A by no detonation at overhaul by OAE - PAAL SCA 11 AMO 15-82
AD 95-26-04 - Rotorcraft Flight Manual - Limitation Section	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	July 15, 1996		C/W, NDF - TCB Astone for: Matt Ry.
AD 96-09-10 - Engine Oil Pump Impellers (454B, 455D, 524, 456)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2018	4784.8 TTAF	N/A by P/N - PAAL SCA 11 AMO 15-82
AD 96-09-29 - Sheave Replacement - (SB-77)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	July 15, 1996		Inspection C/W, NDF - TCB Astone for: Matt Ry.
AD 97-02-14 - Pilot Mismanagement of RPM (Supersedes 96-11-08)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	March 19, 1997		C/W, NDF - TCB Astone
AD 97-15-11 - Piston Pins (527C)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	April 05, 2023	4784.8 TTAF	N/A by P/N - PAAL SCA 11 AMO 15-82
AD 97-25-05 - Mixture Control Idle Cutoff - (SB-82)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	October 26, 2009		C/W as per SB-82 on 25 March 2009 - Matt Willemssen / M753272
AD 98-01-06 - Model MA-3 -3A -3SPA, MA4-SPA Carb inspection (PAM SB MSA-2 rev 1)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	N/A by Date - PAAL SCA 11 AMO 15-82
AD 98-02-08 - Crankshaft Inspection (505B and 530) - Initial	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2015	4784.8 TTAF	C/W, NDF - SCA 15 / PAAL SCA 11 AMO 15-82
AD 98-02-08 - Crankshaft Inspection (505B and 530) - Terminated Action	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	April 05, 2023		
AD 98-17-11 - Crankshaft Inspection	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	August 24, 2018	4784.8 TTAF	Determined to be N/A by S/N at overhaul - PAAL SCA 11 AMO 15-82
AD 98-21-09 - Fuel Tank Vents (SB-83)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	April 03, 2008		C/W by Madonna as SB 83 wo 41846 - Matt Willemssen / M753272
AD 99-02-02 - Flexplate Failure (SB-75)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	March 25, 1999		Fwd Flexplate Rev E installed 10 June 94 as per SB73 - TCB Astone for M408025

Reminder	Status	Current	Time Remaining	Due	Interval	Last Complied Date	Last Complied Time	Method of Compliance
AD 99-07-17 - Sprag Clutch Assembly (SB-85)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	October 26, 2009		C/W as per SB 85 on 25 March 1999 - Matt Willemssen / M753272
AD CF-2005-40 - Non-Conformance of Maintenance on Piston Engines	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	October 26, 2009	4784.8 TTAF	N/A by date Last Overhaul performed by Okanagan Aero Engine - PAAL SCA 11 AMO 15-82
AD CF-90-03R2 - Exhaust type cockpit/cabin heaters (muff) inspect pipes & tubes to detect deterioration - Initial	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	April 05, 2021	5053.9 TTAF	C/W, NDF - TCB Astone for AMO 69-14 ACA 14
AD CF-96-08 - Changes to A/C Flight Manual	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	June 07, 1997		FM amended - Matt Willemssen / M753272
AD CF-98-15 - External Rescue Systems (CAR 702.21)	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	October 26, 2009		N/A no system installed - Matt Willemssen / M753272
AD F-2005-023 - Engines Overhauled by Provence Aero Maintenance	Green		Permanently Complied	Permanently Complied	PCW NON RECURRING	October 26, 2009	4784.8 TTAF	N/A Last Overhaul performed by Okanagan Aero Engine - PAAL SCA 11 AMO 15-82
SB-120 Initial Compliance (A029-2, Tail Rotor Blade, SN: 7627)	Green	TTAF: 6082.2	Permanently Complied	Permanently Complied	25 days or 10.0 TTAF PCW	January 06, 2023	5752.4 TTAF	